Santa, Fe, New Mexico

## MISCELLANEOUS NOTICES

Submit this notice in triplicate to the Oil Conservation Commission or its proper agent before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

NOTICE OF INTENTION TO TEST CASING SHUT-OFF	NOTICE OF INTENTION TO SHOOT OR CHEMICALLY TREAT WELL	
	NOTICE OF INTENTION TO PULL OR	_
NOTICE OF INTENTION TO CHANGE PLANS	OTHERWISE ALTER CASING	_
NOTICE OF INTENTION TO REPAIR WELL	NOTICE OF INTENTION TO PLUG WEL	L
NOTICE OF INTENTION TO DEEPEN WELL		
Hobbs, New M	exico August 29, 1	938
	Place Da	
DIL CONSERVATION COMMISSION,	general grant and a second	
Santa Fe, New Mexico.	DUPLICAT	-
Sentlemen:	a decayihad halom at the	
Continental Oil Company Stat	e J-2 Well No. 2	SE/4
Company or Operator Lease		•••
f Sec. 2 , T. 22-S , R. 36-E	, N. M. P. M.,	Fiel
Lea County.	·	
	PROPOSED PLAN OF WORK	
	LES AND REGULATIONS OF THE COMMISSION	
10-3/4" casing was set in the	subject well at 276' and cement	ed wit
	subject well at 276' and cement	
10-3/4" casing was set in the sacks. After cement has been a lled, hole bailed dry and allowed isfactory proof of complete water	llowed to set 48 hours plug wild to stand dry for 2 hours to car shut off.	l be onstit
sacks. After cement has been a	llowed to set 48 hours plug wild to stand dry for 2 hours to c	l be onstit
sacks. After cement has been a lled, hole bailed dry and allowe isfactory proof of complete water	llowed to set 48 hours plug will do stand dry for 2 hours to cor shut off.  Continental Oil Company	l be onstit
sacks. After cement has been a lled, hole bailed dry and allower isfactory proof of complete water approved	llowed to set 48 hours plug will do stand dry for 2 hours to cor shut off.  Continental Oil Company	l be onstit
sacks. After cement has been a lled, hole bailed dry and allowed isfactory proof of complete water	continental Oil Company	l be onstit
sacks. After cement has been a lled, hole bailed dry and allowed isfactory proof of complete water	continental Oil Company  Company or Operator  By	l be onstit
sacks. After cement has been a led, hole bailed dry and allowed isfactory proof of complete water approved	continental Oil Company	1 be onstit
sacks. After cement has been a lied, hole bailed dry and allower isfactory proof of complete water approved	Continental Oil Company  Company or Operator  By  Position  District Supt.  Send communications regarding well  H. L. Johnston	1 be onstit
sacks. After cement has been a lled, hole bailed dry and allower isfactory proof of complete water approved	Continental Oil Company  Company or Operator  By  District Lupt.	1 be onstit

(x,y) = (x,y) + (x,y

The second of th  $(\mathcal{H}_{\mathcal{H}})^{-1} = (\mathcal{H}_{\mathcal{H}})^{-1} = (\mathcal{H}_{$