

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-08748

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name
ARROWHEAD GRAYBURG
UNIT

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
CHEVRON U.S.A. INC.

8. Well No. 156

3. Address of Operator
P.O. BOX 1150 MIDLAND, TX79702 ATTN: P.R. MATTHEWS

9. Pool name or Wildcat
ARROWHEAD/GRAYBURG

4. Well Location
Unit Letter G : 1990 Feet From The NORTH Line and 1980 Feet From The EAST Line
Section 2 Township 22S Range 36E LEA NMPM County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3549 GE

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐ CASING TEST AND CEMENT JOB ☐
OTHER: ☐ OTHER: DEEPEN, LOG, PERF, ACDZ ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU, POOH W/ PROD. EQUIP. TIH W 4 3/4" BIT WASH TO TD, DRILL FORMATION
3879-3891. SPOT 40 SXS. CMT PLUG, CMT TBG. IN HOLE, SPOT SEVERAL CMT. PLUGS, 135
SXS, CMT.. LEFT TBG. IN HOLE, FISH AT 3760'. CMT AT 3720'.
SIDE TRACKED HOLE AT 3720'-4026. RAN LOGS: DNL-GR-DLL. TST/CSG TO 600 PSI-OK.
SWB/TST. PLUGGED BACK TO 3761' W/50 SXS. CMT. DRILL OUT TO 3927'. ACDZ WITH
1500 GALS. 15% NEFE, OH 3865-3950. PERF OH 3780-3914 W/ 3 1/8" GUNS, 2 JHPF,
0 DEG PHSD. PERF OH 3950-3936. W/ 3 1/8" GUNS, 2 JHPF, 0 DEG. PHSD.
DRILL TO 3960'. ACDZ OH 3730-3960 W/ 1500 GALS. 15% NEFE SWB/TST.
RDMO, RETURN TO PRODUCTION.

WORK STARTED 7-15-91 WORK ENDED 8-19-91.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE P.R. Matthews TITLE TECHNICAL ASSISTANT DATE 8-22-91
TYPE OR PRINT NAME P.R. MATTHEWS TELEPHONE NO. 687-7812

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: