Submit 3 Copies to Appropriate

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103 Revisied 1-1-89

District Office

## **OIL CONSERVATION DIVISION**

			P.O. Bo	x 2088				
DISTRICT I			Santa Fe, Ne	w Mexico 87504-	2088			
	, Hobbs, NM 88240	)						
DISTRICT II  P.O. Drawer Dd, Artesia, NM 88210						API NO. (assigned by OCD on New Wells)		
DISTRICT III	d, Artesia, NM 8821	.0				30-025-08	<del></del>	
	os Rd., Aztec, Nm 8	7410				6. Indicate Typ		EE
						6. State Oil &		
						N/A	Oas Lease No.	
		SUNDRY NOTIC	ES AND REPORTS	S ON WELLS	<del></del>			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A						7. Lease Name or Unit Agreement Name		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"						HARRY LEONARD STATE (NCT-D)		
1. Type of W	/eii·	(FORM C-101)	FOR SUCH PROPOSAL	S.)				
OIL	e	GAS						
WELL		WELL X	OTHER					
2. Name of O	perator		<del> </del>			8. Well No.		<del></del>
	CHEVRON U	J.S.A. INC.					1	
3. Address of		ND TV 70702 A	TTN, D.D. MATTI	EN/C		9. Pool name of		
4. Well Location		ND, 1X /9/02 A	TTN: P.R. MATTH	EVVS		SOUTHEO	NICE SR-QN	
Unit Letter		H :	1650 Feet From The	NORTH	Line and	33	O Feet From The EAST	T Line
Section	3	3	Township	22S	Range	36E	NMPM LEA	County
			10. Elevation	Show whether DF, RKB, RT,	GR, etc.)			
				3545 GE	0.1 0	_		
11	NOTICE OF I	INTENTION TO:	te box to indecate Nati	ure of Notice, Report, or	Other Data QUENT REF	OPT OF		
PERFORM REM		PLUG AND ABANE	OON [	REMEDIAL WORK	ZOLIVI NEI	l	ALTER CASING	
TEMPORARILY		CHANGE PLANS		COMMENCE DRILLING OPN	15	1	PLUG AND ABAN.	
PULL OR ALTER				CASING TEST AND CMT JO	<del>-</del>	i	TEGG AND ABAN.	
OTHER:		CK PENROSE	X	OTHER:		J		
		TE IN QUEEN						
12. Describe P			e all pertinent details, and g	ve pertinent dates, including			· · · · · · · · · · · · · · · · · · ·	
esticated da	ate of starting any pr	oposed work) SEE RULE 1	103.					
MIRU, POOH WITH PRODUCTION EQUIP.								
✓ SET CIBP AT 3000' AND DUMP BAIL 35' OF CEMENT ON TOP.								
	PERF WITH 4" GUNS AT QUEEN FORMATION.							
ACIDIZE PERFS AND SWAB TEST.								
	FRAC QUEEN FORMATION AND FLOW WELL BACK.							
	CLEAN OUT	SAND IF NEEDED	D.					
	TIH WITH TE	BG. AND PACKER	<b>1.</b>					
	RETURN TO	PRODUCTION.						
			e to the best of my knowled	-	_			
SIGNITURE		Master	TITLE	TECH. ASSISTAN	<u>T</u>	DATE:	6/30/92	
TYPE OR PRINT	NAME	P.R. MATTHE	EWS			TELEPHONE NO.	(915)687-7812	
	GRIGINAL	SIGNED BY JERR	Y SEXTON				(0.0,00, ,012	
	DIS	TRIGT I SUPERVIS	OR				HH 00 40-	
APPROVED BY	F APPROVAL, IF AN		TITLE		<del></del>	DATE	JUL 06'92	