Submit 3 Copies to Appropriate

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revisied 1-1-89

District Office	OIL CONSER	VATION DIVISION	
DISTRICT		_{Вох} 2088 lew Mexico 87504-2088	
DISTRICT P.O. Box 1980, Hobbs, NM 88240		New Mexico 67304-2008	
DISTRICT II			API NO. (assigned by OCD on New Wells)
P.O. Drawer Dd, Artesia, NM 882	10	30-025-08765	
DISTRICT III 1000 Rio Brazos Rd., Aztec, Nm 87410			Indicate Type of Lease STATE
			6. State Oil & Gas Lease No.
			B-1732
SUNDRY NOTICES AND REPORTS ON WELLS			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"			7. Lesse Name or Unit Agreement Name HARRY LEONARD (NCT-D)
(FORM C-101) FOR SUCH PROPOSALS.)			1
Type of Well: OIL	GAS		
WELL X	WELL OTHER		
2. Name of Operator CHEVRON U.S.A. INC.			8. Weil No. 14
3. Address of Operator			9. Pool name or Wildcat
P.O. BOX 1150 MIDLAND, TX 79702 ATTN: NITA RICE			EUNICE SOUTH SR/QUEEN
4. Well Location Unit Letter	N : 660 Feet From	The SOUTH Line and	1980 Feet From The WEST Line
Section 3	Township	22S Range	36E NMPM LEA County
	10. Elevat	ion(Show whether DF, RKB, RT, GR, etc.	
		3571' GL	
11 Check Appropriate Box to Indecate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTER CASING			
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPNS.	PLUG AND ABAN.
PULL OR ALTER CASING	-	CASING TEST AND CMT JOB	
OTHER:		OTHER:	
12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including esticated date of starting any proposed work) SEE RULE 103.			
WORK DONE 9-28-92 THRU 9-30-92 TIH AND SET CIBP AT 3720', LOAD AND TEST ANN., CAP WITH 35' CMT. COVERS QUEEN PAY.			
SET BALANCED PLUG F/3440-3040(40 SXS.) COVERS YATES AND 7-RIVERS PAY.			
SHOOT HOLES AT 1725', BREAK CIRC BETWEEN 5-1/2" & 8 5/8" CSG.SET CICR AT 1530'			
SQUEEZE WITH 50 SX, CMT AND LEAVE 35' ON TOP, PLUG COVERS RUSTLER AND YATES.			
SHOOT HOLES AT 457', BREAK CIRC BETWEEN 5-1/2" & 8 5/8" CSG, CEMENT WITH 115 SXS.			
LEAVE 5.5" CASING FULL OF CEMENT.			
CUT OFF WELLHEAD AND INSTALL P & A MARKER.			
10# P & A MUD PLACED BETWEEN ALL CMT. PLUGS.			
CHANGE WELL STATUS TO P & A.			
I hereby certify that the information	n above is true and complete to the best of	my knowledge and belief. TECHNICAL ASSISTANT	DATE: 10/19/92
_ / W		TECHNICAE ASSISTANT	
TYPE OR PRINT NAME	NITA RICE		TELEPHONE NO. 915 687-7436
APPROVED BY //// /		Giller Caraman	DEC 2 8 '92
	$T_{I}^{\prime\prime}$	•	