Submit 3 Copies to Appropriate

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revisied 1-1-89

MAY 22'92

DATE

OIL CONSERVATION DIVISION

District Office P.O. Box 2088 DISTRICT I Santa Fe, New Mexico 87504-2088 P.O. Box 1980, Hobbs, NM 88240 DISTRICT !! API NO. (assigned by OCD on New Wells) P.O. Drawer Dd, Artesia, NM 88210 30-025-08765 DISTRICT III 5. Indicate Type of Lease 1000 Rio Brazos Rd., Aztec, Nm 87410 STATE X FEE 6. State Oil & Gas Lease No. B-1732 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG B 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" HARRY LEONARD (NCT-D) (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: OIL GAS WELL X WELL OTHER 2. Name of Operator 8. Well No. CHEVRON U.S.A. INC. 3. Address of Operator 9. Pool name or Wildcat P.O. BOX 1150 MIDLAND, TX 79702 ATTN: P.R. MATTHEWS **EUNICE SOUTH** J(44 4. Well Location Unit Letter 660 Feet From Th SOUTH Line and 1980 Feet From The **WEST** Line Section Township 22S 36E Range LEA NMPM County 10. Elevation(Show whether DF, RKB, RT, GR, etc.) 3571' GL Check Appropriate Box to Indecate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON IX! REMEDIAL WORK ALTER CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABAN. PULL OR ALTER CASING CASING TEST AND CMT JOB OTHER: OTHER: 12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including esticated date of starting any proposed work) SEE RULE 1103. IT IS PROPOSED TO: PLUG AND ABANDON WELL TIH AND SET CIBP AT 3720', LOAD AND TEST ANN., CAP WITH 35' CMT. COVERS QUEEN PAY. SET BALANCED PLUG F/3440-3040(40 SXS.) COVERS YATES AND 7-RIVERS PAY. SHOOT HOLES AT 1725', BREAK CIRC BETWEEN 5.5" & 8 5/8" CSG.SET CICR AT 1530' SQUEEZE WITH 50 SX. CMT AND LEAVE 35' ON TOP. PLUG COVERS RUSTLER AND YATES. SHOOT HOLES AT 457', BREAK CIRC BETWEEN 5.5" & 8 5/8" CSG, CEMENT WITH 115 SXS. LEAVE 5.5" CASING FULL OF CEMENT. CUT OFF WELLHEAD AND INSTALL P & A MARKER. 10# P & A MUD WILL BE PLACED BETWEEN ALL CMT. PLUGS. CHANGE WELL STATUS TO P & A. 三 印 1.の語節 24 L TEXT OF THE PAR CHOS I hereby certify that the information above to true and complete to the best of my knowledge and belief. SIGNITURE TITLE TECH. ASSISTANT DATE: 5/20/92 TYPE OR PRINT NAME P.R. MATTHEWS TELEPHONE NO (915)687-7812

·

TITLE

APPROVED BY CONDITIONS OF APPROVAL, IF ANY: