

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B-1506	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER Dual Oil-Gas well		7. Unit Agreement Name
2. Name of Operator Atlantic Richfield Company		8. Farm or Lease Name State 157 "G"
3. Address of Operator P. O. Box 1710, Hobbs, New Mexico 88240		9. Well No. 3
4. Location of Well UNIT LETTER A 990 FEET FROM THE North LINE AND 990 FEET FROM THE East LINE, SECTION 5 TOWNSHIP 22S RANGE 36E NMPM.		10. Field and Pool, or Wildcat Eunice 7Rivers On So. Jalmat Gas
15. Elevation (Show whether DF, RT, GR, etc.) 3594' GR		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 3900', PBD 3884'. Presently completed in Jalmat Gas zone from perfs 3193-3571'. Eunice 7Rivers Queen oil perfs 3809-3827' & 3836-3840' w/DR plug in 415D pkr set @ 3600' and capped w/2 sx sand & 2 sx cmt. CIBP set @ 3103' above Jalmat perfs. 2000# master valve on wellhd. No tubing in hole.  
10-3/4" OD 28.52# slip jt csg set @ 311' & cmtd w/300 sx.  
7" OD 17 & 20# csg set @ 3900' & cmtd w/200 sx. DV tool @ 1590' & cmtd w/100 sx. TOC above DV tool @ 1090' from surface. All producing zones in this well have been depleted and no other zones of interest exist. Propose to P&A in the following manner:  
1. Rig up, kill well, install BOP.  
2. Run in hole w/2-3/8" EUE tbg OE and spot 10 sx approx 50' Cl C cmt on top of CIBP @ 3103'.  
3. Pull up & spot 25 sx Cl C cmt approx 140' cmt plug across top of salt @ 1666'.  
4. Pull up & spot 10 sx Cl C cmt @ surface, install regulation dry hole marker, clean & level location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Ed Roy Frost TITLE Dist. Drlg. Supv. DATE 11/21/75

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: