			S. COMMISSION MJM
Form 3160 5 (June 1990)	UNITED ST DEPARTMENT OF BUREAU OF LAND	THE INTERIOR	Al Control Bureau No. 1004-0135 Expires: March 31, 1993 S. Lesse Designation and Serial No. NMLC030132 - A
Do not use this fo U	6. If Indian, Allottee or Tribe Name		
	SUBMIT IN TF	7. If Unit or CA, Agreement Designation	
I. Type of Well		UNIT A	
Oil     Gas       Well     Well       Well     Well	TOM CLOSSON #2		
SOUTHWEST F	9. API Well No. 30-025-08802		
P.O. BOX 11	10. Field and Pool, or Exploratory Area		
4. Location of Well (Footag	JALMAT TANSILL YT SR 11. County or Parish, State		
SEC. 6, T-22S, R-36E UNIT I, 1980 FSL AND 660 FEL			11. COURY OF Parisa, State
UNIT 1, 198	SO FEL AND OUG TEL		LEA COUNTY, NM
IZ. CHECK	APPROPRIATE BOX(s) TO	INDICATE NATURE OF NOTICE, RE	EPORT, OR OTHER DATA
TYPE OF SUBMISSION TYPE OF AG			TION
Notice o	f Intent	Abandonment	Change of Plans
Subseque	ent Report	Recompletion Plugging Back Casing Repair	New Construction Non-Routine Fracturing Water Shut-Off
Final At	pandonment Notice	Altering Casing Chief Casing Conter <u>CASING INTEGITY</u> T	EST Conversion to Injection EST Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
PROCEDURE	ROCEDURE FOR TESTING E AND WELLBORE DIAGRAM A <i>393-3412</i> Y BLM (505) <del>887-6544</del> 4		BUREAU OF LAND
in to the second			IVED'я с5 Л1 '94 км. нонт.
	foregroing is true and correct	Prailatory appt	in 12-16-94
Signed	or State office use)		
Approved by	G. SGD.) JOE G. LARA	PETROLEUM ENGI	1821 Der 1/11/95
Conditions of approval,		- Anna maria and the same	Phyling of the
Title 18 U.S.C. Section 100	01, makes it a crime for any person knowing matter within its jurisdiction.	gly and willfully to make to any department or agency of th	e United States shy false, fictitious or fraudulent statement

. .

#### Tom Closson #2 1980' FSL & 660' FEL, Sec. 6-T22S-R36E Lea County, New Mexico

### Procedure to Test Well for Casing Integrity

- 1. Contact BLM in Carlsbad at 505-887-6544 48 hours before beginning procedure.
- 2. MI RU WU. POH with rods and pump. ND WH and NU BOP. POH with tubing and production equipment.
- 3. RIH with RBP on tubing and set at 3100'. Close rams and pressure test casing to 500 psi for 30 minutes utilizing a chart. Maximum pressure bleed off is 10%. Send chart to Midland office.
- 4. Latch RBP and POH with RBP. RIH with tubing open ended. ND BOP and NU wellhead.

Doug "Keath Ney

Area Supervisor

# PECENED

JAN 10 165 CCD Addass OFFICE



(Rev. 5/23/94)

#### BUREAU OF LAND MANAGEMENT CARLSBAD RESOURCE AREA

## Temporary Abandonment of Wells on Federal Lands

#### Conditions of Approval

According to 43 CFR 3162.3-4-c, " No well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer".

Temporary Abandonment (TA) status approval requires a successful casing integrity test as follows:

- Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County call (505) 887-6544 ; for wells in Lea County call (505) 393-3612.
- 2. A bridge plug or packer shall be set at a maximum of 50 feet above any open perforations or open hole.
- 3. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
- 4. The production casing shall be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leak-off.

Wells that successfully pass the casing integrity test will be approved for Temporary Abandonment (TA) status for 12 months provided that the operator:

1. Submits a subsequent Sundry Notice requesting TA approval,

2. Attaches a clear copy or the original of the pressure test chart,

3. And attaches a detailed justification why the well should not be plugged and abandoned.

The TA status could be extended without another casing integrity test provided there was no leak-off during the test.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

# 

148 1 3 HUBS

OFFICE

•