

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

FEB 11 3 24 PM '66

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Gulf Oil Corporation	8. Farm or Lease Name J. H. Day
3. Address of Operator Box 670, Hobbs, New Mexico	9. Well No. 3
4. Location of Well UNIT LETTER N 330 FEET FROM THE South LINE AND 2310 FEET FROM THE West LINE, SECTION 6 TOWNSHIP 22-S RANGE 36-E NMPM.	10. Field and Pool, or Wildcat Jalnat
15. Elevation (Show whether DF, RT, GR, etc.) 3593 GL	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

Plugged and abandoned.

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3736' PB, 3835' TD.

Killed well with 100 barrels of water. Ran CI BP on tubing and set at 3482'. Loaded hole with mud. Spotted 10 sack cement plug on top of BP. Tested casing and BP with 500#. OK. Spotted 10 sack cement plug from 50' to surface. Cleaned location and installed dry hole marker. Plugged and abandoned February 11, 1966.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED _____ TITLE **Area Production Manager** DATE **February 11, 1966**

APPROVED BY *Jessie A. Clement* TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: