W MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELL

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut-offs, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

Indicate	nature of rep	ort by checking below		
REPORT ON BEGINNING DRILLING OPERATIONS	- 	REPORT ON REP	LIRING WOLL	
REPORT ON RESULT OF SHOOTING AR CHEMICAL TREATMENT OF WELL	x	REPORT ON PULI ALTERING CA	ING OR OTHERWIS	E .1 1970
REPORT ON RESULT OF TEST OF CASI: SHUT-OFF	VG	REPORT ON DEER	SING TENING	
REPORT ON RESULT OF PLUGGING OF V	WELL	Packer install	ation	OFFICEN
	Hobbs, Ne			
OIL CONSERVATION COMMISSION,		W Mexico, Ju		
Santa Fe, New Mexico. Gentlemen:			DUPLIC	
Following is a report on the work done an ulf 011 Corp-Gypsy Prodn. Div			_	
Company or Operator SE/4 SW/4 of Sec.		Lease		
South Bunice Field,				
The dates of this work were as follows:				
Notice of intention to do the work was (wanned approval of the proposed plan was (wa	as not) submit	ted on Form C-102 on	morde)	19
at 3811' uly 11, 1939, acid treated with reduction tests: Before, avg. thru 1/2" & 3/4" cheke After: Flowe wide open, to Name	54 bbls of set wide ope	l daily with 1,	329,825 cu. ft.	i/4" chokes
	P9nd	I hereby swear or a	firm that the inform	ation given above
Subscribed and sworn to before me this		is true and correct.		
day of July	, ₁₉ 39	Name CC	Preces	ung-
		Position Dist	rict Superinten	dens
Notar	y Public	Representing Gulf		Prodn. Div.
My Commission expires February 25,	1942.	Address Hobb		
Remarks:			Roy n	arbrou Name

OIL & GAS INSPECTOR