Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT! P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION P.O. Box 2088

WELL API NO.

DISTRICT II	Santa Fe, New Mexico	87504-2088	30-025-08817
P.O. Drawer DD, Artesia, NM 88210	Danial LO, NOW IVICATION	07504-2000	5. Indicate Type of Lease
DISTRICT III			STATE X FEE
1000 Rio Brazos Rd., Aziec, NM 87410			6. State Oil & Gas Lease No.
SUNDRY NOTI	CES AND REPORTS ON WE	LLS	
(DO NOT USE THIS FORM FOR PRO	POSALS TO DRILL OR TO DEEPER	YOR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
UIFFERENT RESER	IVOIR. USE "APPLICATION FOR PE 101) FOR SUCH PROPOSALS.)	RMIT .	" Louis Falle of Olle Agreement Falle
1. Type of Well:	101) FOR SOCH PROPOSALS.)		
OL O . QU O			
	OTHER		State A A/C 2
2. Name of Operator			8. Well No.
Hal J. Rasmussen Oper	ating, Inc.		_5
3. Address of Operator			9. Pool name or Wildcat
Six Desta Drive, Suit	e 5850, Midland, Texas	79705	Jalmat Tnsl-Yts-7R
1			
Unit Letter _A : _66	O Feet From The North	Line and _660	Feet From The East Line
		•	
Section 7	Township 22S R	inge 36 E p	MPM Lea County
	Township 22S Ri	DF, RKB, RT, GR, etc.)	
	3610 G.L.		<i>\(\(\(\(\(\(\(\(\(\(\)\\\\\\\\\\\\\\\\</i>
11. Check A	appropriate Box to Indicate	Nature of Notice, Re	PORT or Other Data
NOTICE OF INT	ENTION TO:		
No not of mi	ENTION TO.	208	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
THE STATE OF THE S	_		E AETENING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING		CASING TEST AND CE	USUT ION
_		OWNING LEST WIND CEL	MENT JOB [_]
OTHER:		OTHER:	
12. Describe Proposed or Completed Operations (Clearly state all partiage ducits and aircraft an			
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.			
	Current Status - Jal	mat	
D 1 0			
Proposed Operations			
1) 01			
1) Clean out hole			
2) Perforate Tansill	-Ytaes 2935-3200		
3) Acidize.			
4) Frac.			
5) Put on pump.			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
a nectory coming that the information above is true a	and complete to the best of my knowledge and	bdia.	
SIGNATURE	<u>X</u>	Agent	PATE 12/07/89
			DATE
TYPEOR PRINT NAME Jay Che	erski		ТЕГЕРНОКЕ НО. 915-687-166

(This space for State Use)

ATTROVED BY-

ORIGINAL SIGNED BY JERRY SEXTON

DISTRICT I SUPERVISOR

- TITLE -

DEC 1 2 1989

DATE -

CONDITIONS OF APPROVAL, IF ANY: