

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
310 Old Santa Fe Trail, Room 206
Santa Fe, New Mexico 87503

WELL API NO. 30-025-08819
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-1506
7. Lease Name or Unit Agreement Name State 157 "B"
8. Well No. 2
9. Pool name or Wildcat Jalmat

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Black Resources, Inc.	
3. Address of Operator 1100 Mustang Trail, Granbury, Texas 76049-5621	
4. Well Location Unit Letter <u>F</u> : <u>1650</u> Feet From The <u>North</u> Line and <u>2310</u> Feet From The <u>West</u> Line Section <u>7</u> Township <u>22S</u> Range <u>36E</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3823 GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well was reentered on March 18, 1993. Ran tubing and tag fill @ 3523' and tagged bad casing at 3523'. Wash sand from 3529' to 3666'. Circ hole clean. Received no show of oil or gas. Rig up Black Warrior Wireline and perf 7" csg. w/select Fire csg. from 3539' to 3632' - 1 spf w/14 holes - Rig wireline down - trip in hole w 7" Baker pkr. and 112 joints 2 7/8" tubing. - Set pkr. @ 3479' - Strat swabbing w/Fluid 1200' from surface - swab tub. dry w/no show of gas - hook up Acid Engineers and pump 1000 gallons 7 1/2% NaFe Acid and 28 ball sealers and Flush w/50,000# 12/20 Brady Sand and 20,000 gallons gel water - max rate 22 BPM - max. pres. 3040# - ISIP 1300# - 30 minutes vac. load to receive 471 bbls. Closed well in and shut down. Tubing on Vac. - Run swab and find fluid 1000' from surface - swab well dry - well has a steady Blow off of gas for 5 to 10 minutes - then loads up w/water. Keep well swabbed dry-running swab over 30 minutes w/100' fluid entry - total fluid received swabbing = 26 bbls - close well in - load to rec. = 445 bbls. Pumped down tubing and drilling with no returns - drill cmt. and junk from 3660' to 3700'. Trip out of hole and lay drill collars down - Rig reverse unit down. Tag bot on ns space tubing 27' off bottom. Plug up wellhead run pump and rods in hole. Seat and space pump and hang well on w/good pump action.

SIGNATURE William D. Black TITLE President DATE 11/15/95

TYPE OR PRINT NAME William D. Black

TELEPHONE NO. (817) 579-1144

(This space for State Use) ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

NOV 21 1995