

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-101
Revised 10-1-73

5a. Indicate Type of Lease	
State ☐	Fee ☐
5. State Oil & Gas Lease No.	
7. Unit Agreement Name	
8. Farm or Lease Name	
State A A/C 2	
9. Well No.	
20	
10. Field and Pool, or Wildcat	
Jalmat Tansil Yates	
7 Rivers	
12. County	
Lea	

SUNDRY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT - (FORM C-101) FOR SUCH PROPOSALS.

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator
Sun Exploration & Production Co.
3. Address of Operator
P. O. Box 1861 - Midland, Texas 79702
4. Location of Well
UNIT LETTER J 1980 FEET FROM THE South LINE AND 1980 FEET FROM THE East LINE, SECTION 7 TOWNSHIP 22-S RANGE 36-E N.M.P.M.

15. Elevation (Show whether DF, RT, GR, etc.)

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐
PULL OR ALTER CASING ☐	OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐	ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐	OTHER Add perfs & acdz ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 5-10 MIRU DA&S WS/POH w/Rods & Pump/POH w/2-3/8 pump set up/RIH w/5½ RDG on 2-7/8 tbg/set PKR 372 @ (500#) western acdz Jalmat 7 Rivers perfs 3787-3815 w/1000 gal 15% NEFE w/80 ball sealers. Ball action 2800-2100 did not ball out.
- 5-11 TR BO at first of swab.
- 5-12 POH w/PKR & tbg/RIH w/5½ cmt ret (Howco) set @ 3780 (500#) Howco EIR in perfs 3797-3815 5 BPM @ 1400/Howco squeeze perfs 3797-3815 w/75sx C w/.3% Halad 4 followed by 100 sx "C" w/3# salt Disp 36sx in form Final TP 2000 & holding snap out of ret rev out 135 sx cmt/POH.
- 5-13 CRC perf Seven Rivers Set I 3722-30, 3737-59 2JSPF (62 holes) w/4" csg gun 23 gram (.47EH) by Schlum GR-N/RIH w/5½ RDG on 2-7/8 tbg to 3759/spot 50 gal 15% NEFE 3759-3709/raise & set PKR 3619 (500#)/Western Acdz Perfs 3722-59 w/1500 gal 15% NEFE w/93 ball sealers/BD. Ball action 1000-2300 did not ball out/lower PKR thru perfs Reset @ 3619.
- 5-15 POH w/RDG PKR and 2-7/8 tbg Howco cmt retainer and 2-7/8 tbg 3702 ET into perfs 3722-3759 a 6 BPM at 500 PSI. Howco sqzd Jalmat perfs 3722-3759 w/50 sxs "C" w .3% Halad 4 followed by 100 sxs "C" 3# salt, displace 135 sxs into formation FP 1000 PSI, holding, snapout of retainer. Rev out 12 sxs cmt, POH w/2-7/8 tbg and setting tool.

(cont.)

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Dee Ann Kemp
ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR

TITLE Acct. Asst. II

DATE 5-25-83

PROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE MAY 31 1983