

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator Sun Exploration & Production Co. 3. Address of Operator P. O. Box 1861, Midland, TX 79702 4. Location of Well UNIT LETTER <u>I</u> <u>1980</u> FEET FROM THE <u>south</u> LINE AND <u>660</u> FEET FROM THE <u>east</u> LINE, SECTION <u>8</u> TOWNSHIP <u>22-S</u> RANGE <u>36-E</u> NMPM. 15. Elevation (Show whether DF, RT, GR, etc.)	7. Unit Agreement Name 8. Farm or Lease Name State "A" A/C 2 9. Well No. 24 10. Field and Pool, or Wildcat South Eunice Seven Rvrs Queen 12. County Lea
--	--

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <u>Reperf & Acdz</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1-25-85 POH w/rods & Pump
1-26-85 RIH w/ 3-7/8 bit, 4 - 3-1/8-DC's on 2-3/8 WS, tagged @ 3787, cleaned out to 3801, could not drill deep, rec scale 3787-3801 & metal @ 3801, circ clean & POH to 2000'
1-29-85 FOH w/bit TIH w/3-15/16" cutrite shoe, 31 3-13/16" WP 4 - 3-1/8" DC's on 2-3/8" WS mill over junk from 3801' to 3841' WP plugged POH rec approx. 30' of twisted up tbg in WP TIH w/3-7/8" bit to 3600'
1-30-85 lwr bit CO fill from 3841' to 3863' PBD circ clean POH perf 3758-90, 3800-04, 3810-50 1 JSP2F (41 holes) 3-1/8" csg gun 12 GC .36 EHD TIH w/4-1/2" pkr on 2-3/8" WS to 3600'
1-31-85 Lwr pkr to 3850, Howco spot 4 bbls 15% NEFEHCL 3850-3600, PU & set pkr @ 3644, trap 500 on csg, Howco acdz perfs 3666-3850 w/4000 gals 15% NEFEHCL + 81 RCNBS
2-5-85 TIH w/2-3/8" prod tbg & pumping setup TS 3832' SN 3797' RIH w/2"X1 1/2"X12" pump on 66 rod string
2-6-85 Started pumping
2-20-85 24 hrs., P, 8 BO, 143 BW, 34 MCF, GOR 4250/1, 12X64X1 1/2, FL 3658' from surf

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Dee Ann Kemp TITLE Associate Accountant DATE 2-28-85

ORIGINAL SIGNED BY JERRY SECTON

APPROVED BY DISTRICT 1 SUPERVISOR TITLE _____ DATE MAR - 6 1985

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

MAR -5 1985

OFFICE
HOUSE OFFICE