Remarks:

## NEV. MEXICO OIL CONSERVATION COMP. SSION

## Santa Fe, New Mexico

## MISCELLANEOUS REPORTS ON WELL

submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut-offs, result of plugging of well, Can other important operations, even though the work was witnessed by an agent of the commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

Indicate natu			additional instructions	
· · · · · · · · · · · · · · · · · · ·	re of repor	rt by checking be	elow:	
REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON REP	PAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		REPORT ON PUI	LLING OR OTHERWISE	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF	x	REPORT ON DEE	EPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL				
	January (		Fort Worth,	
OIL CONSERVATION COMMISSION, Santa Fe, New Mexico		Place		Date
Gentlemen:				
Following is a report on the work done and the	results ob	tained under the	e heading noted above	at the
Texas Pacific Coal & Oil Co., State	e "A" Ac		Well No. 24	in the
Company or Operator SE of Sec.	т	22-N	, <sub>R.</sub> 36-E	, N. M. P. M.,
So. Funice Field,		Lea		County
The dates of this work were as follows:				
Notice of intention to do the work was (was not and approval of the proposed plan was 222 not)  DETAILED ACCOUNT OF	obtained.	(Cross out incor	rect words.)	
Drilled plug at 10:00 P. M. January	3, 1943	, and tested	i 7" casing with	900 lb. pump
Drilled plug at 10:00 P. M. January				900 lb. pump
pressure before and after drilling.	plug. P	ipe tested (		900 lb. pump
pressure before and after drilling.  Witnessed by E. O. Beatty,	plug. P	ipe tested (		
pressure before and after drilling.	plug. P	ipe tested (	O. K.	Title
pressure before and after drilling.  Witnessed by E. O. Beatty,	plug. P	1 Company Company I hereby sw above is tru		Title
pressure before and after drilling.  Witnessed by E. O. Beatty, Name	plug. P	1 Company Company I hereby sw	vear or affirm that the le and correct.  He Se Ma	Title
Witnessed by E. O. Beatty,  Name  Subscribed and sworn to before me this	plug. P	1 Company Company I hereby swabove is tru Name Position	vear or affirm that the le and correct.  Le Se Magent  gent	Title given

Title