

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

| | |
|------------------------|--|
| NO. OF COPIES RECEIVED | |
| DISTRIBUTION | |
| SANTA FE | |
| FILE | |
| U.S.G.S. | |
| LAND OFFICE | |
| OPERATOR | |

| | |
|---|------------------------------|
| 5a. Indicate Type of Lease | |
| State <input checked="" type="checkbox"/> | Fee <input type="checkbox"/> |
| 5. State Oil & Gas Lease No. | |

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐ GAS WELL ☐ OTHER- TA'd Injection Wells

Name of Operator
Sun Exploration & Production Company

Address of Operator
P.O. Box 1861 Midland, Texas 79702

Location of Well
UNIT LETTER E 1980 FEET FROM THE North LINE AND 1980 FEET FROM
THE West LINE, SECTION 8 TOWNSHIP 22 RANGE 36 NMPM.

7. Unit Agreement Name

8. Farm or Lease Name
State A A/C 2

9. Well No.
51

10. Field and Pool, or Wildcat
Eunice 7 Bvrs Queen S

15. Elevation (Show whether DF, RT, GR, etc.)

12. County
Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☒
OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-12 MIRU POH & L.D. rods & pump, rods corroded to junk condition

9-13 POH w/2-3/8 short string leaving 2-3/8 SN in hole/ Found 2-3/8 long string parted POH w/ 3275' leaving approx 15 jts & PKR ass'y in hole/ RIH w/5-3/4 x 3-1/16 OS 1 jt 5-3/4 wash pipe BS jars 4 - 3 1/2 DCs on 2-7/8 WS Tag & fish @ 3275/ POH w/no recovery/ RIH w/same assy tag & work over fish to 3285/ POH rec 5' 2-3/8 tbg w/severe corrosion

9-14 RIH w/6-1/8 cone buster Mill 4 - 4-1/8 DCs on 2-7/8 WS tag & Mill Iron sulfide & metal 3275-3310 35' in 5-1/2 hr circ clean PU to 3200

9-17 Fin TOH w/bit TIH w/6" cutrite shoe, 194' - 5-3/4" WP, oil jars, 6 4-1/8" DCs on 2-7/8" tbg tag & wash over fish from 3309' to 3337' WP plugged TOH rec. pieces of 2-3/8" tbg jammed in shoe TIH w/ 5-3/4" cutrite shoe, 163' - 5-3/4" WP oil jars, 6 - 4-1/8" DCS on 2-7/8" tbg to 3212'

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Dee Ann Kemp

TITLE Associate Accountant

DATE 10/01/85

APPROVED BY E. J. ...
CONDITIONS OF APPROVAL, IF ANY:

TITLE OIL & GAS INSPECTOR

DATE MAR 8 - 1988

RECEIVED

OCT - 9 1985

O.C.D.
HOBBY OFFICE