

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐ GAS WELL ☐ OTHER- TA'd Injection Well

7. Unit Agreement Name

Name of Operator  
Sun Exploration & Production Company

8. Farm or Lease Name  
State A A/C 2

Address of Operator  
P.O. Box 1861 Midland, Texas 79702

9. Well No.  
51

Location of Well  
UNIT LETTER F 1980 FEET FROM THE North LINE AND 1980 FEET FROM  
THE West LINE, SECTION 8 TOWNSHIP 22 RANGE 36 NMPM.

10. Field and Pool, or Wildcat  
Eunice 7 Bvrs Queen S

15. Elevation (Show whether DF, RT, GR, etc.)

12. County  
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

During a workover we could not clean out a fish below 3455' called Jerry Sexton on 9-17-85 and requested permission to plug this well.

He agreed to the following procedure:

1. Spot cmnt plug below Yates 3455-3370 and tag.
2. Spot plug across Yates to at minimum of 50' above Yates perms 3192-3370 & Tag.
3. Circ hole with mud.
4. Perf. sqz hole @ 260' & sqz across 9-5/8 casing seat.  
or  
Cut & pull 7" csg below 362' & spot open hole cmnt plug 50' inside & outside of 9-5/8 casing seat @ 312'. WOC & tag
5. Spot 30' surf plug. Cut off W.H. & weld on steel plate.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED DeAnn Kemp TITLE Associate Accountant DATE 10/1/85

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE OCT 1 0 1985

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

OCT -9 1985

O.C.D.  
HOBBS OFFICE