State of New Mexico Largy, Minerals and Natural Resources Departm.

Form C 103 Revised 1-1-89

DISTRICT	OIL CONSERVATION DIVISION		WELL API NO.		
DISTRICT I P.O. Box 1980, Hobbs, NM S8240	P.O. Bo		30-025-08841		
P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Me	exico 87504-2088	5. Indicate Type of		FEE
DISTRICT TII 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas		
(DO NOT USE THIS FORM FOR PRODIFFERENT RESEL (FORM C	ICES AND REPORTS ON OPOSALS TO DRILL OR TO DE RVOIR. USE *APPLICATION FO 101) FOR SUCH PROPOSALS	EPEN OR PLUG BACK TO A OR PERMIT	\ ////////////	Unit Agreement Name	'''''''''''''''''''''''''''''''''''''
1. Type of Well: Oil Well Gas Well Well	OTHER			State 'A' A/C 2	
2. Name of Operator Raptor Reso	urces Inc		8. Well No.	54	
3. Address of Operator	21069, 1110.		9. Pool name or W	/ildcat	
901 Rio Grande, Austin, TX 7	8701		Jalmat, Tnsl, Yt	s, 7-Rivers (Pro G	as) (79240)
4. Well Location Unit Letter O 660	Feet From The Soi	uth Line and 1	980 Feet From	The East	Line
Section 8	Township 22S	Range 36E	NMPM	Lea	County
	10. Elevauon (Show w	hether DF, RKB. RT, GR, ctc.)		///////////////////////////////////////	////////
Check A	Appropriate Box to Indic	cate Nature of Notice, I	Report, or Other	Data	
NOTICE OF INT		SUE	SEQUENT R	EPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	\boxtimes	ALTERING CASING	;
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLIN	G OPNS.	PLUG AND ABAND	ONMENT
PULL OR ALTER CASING		CASING TEST AND C	EMENT JOB		_
OTHER:		OTHER			
12. Describe Proposed or Completed Opwork) SEE RULE 1103. 8-17-99 MIRU. Pooh W/ tbg, rods & Perf the Seven Rivers W/ 2 SPF @ 3 3662, 3664 & 3666' for a total of 40 Rvrs W/ 2750 g 7.5% NEFE HCl aci CO2 & 401 MCF N2 with 191,000# to 3400' SION. Lowered tbg cleaned 8-31-91 RDMO. Well returned to p	t pump. GIH W/ 7" csg scra 480, 3482, 3484, 3496, 349 holes. GIH W/ 7" packer se d W/ 100 BS. Reset packer 12/20 Brady sand. GIH rele l out to 3660'. GIH W 2 3/8' roduction.	aper ot 3750'. pooh. GIH V 18, 3501, 3530, 3532, 3534 t @ 3681', spot 250 g acid @ 3363'. Frac W/73,000 hase packer & POOH. Tag	// CIBP set @ 376 , 3560, 3562, 3580 across perfs, Set pg linear gel foame sand fill @ 3462',	0' W/ 10' of cemer , 3582, 3628, 3630 backer @ 3363', and d to 70 quality W/ clean out to3714,	nt on top. 0, 3660, cidize 7 / 127 T
12. I hereby certify that the information above is trustional signature Signature Bill R. Keathly	e and complete to the best of my knowled		gent for Raptor	DATE 12- TELEPHONE NO. 91	4-99 5-697-1609
(this space for State Use)	ORIGINAL SIGNED BY	,		Wille S	e fifty;
APPROVED BY	G/27 / 24 FIF	_ TITLE		DATE	
CONITIONS OF APPROVAL, IF ANY:					