


SCOUT REPORT
NEW MEXICO OIL CONSERVATION COMMISSION



Company J. & P. Coal & Oil
Farm Name State 2, Sect 2 Well No. 38
Sec. 9 Twp. 22 Range 36 County Lea
Feet from Line: N. 1980 S. E. 1980 W.
Elevation 3565 Method F
Contractor _____
Spudded 11-28-46 Completed 3-13-47

AMOUNT
CASING & CEMENTING RECORD

Size	Feet	Inches	Sax Cement
<u>12 1/2</u>	<u>27 1/2</u>		<u>250</u>

TUBING RECORD

PACKER

ACID RECORD

Gals.
500

Top Pay 3510

TA	TG
TX	TSA
TCA	TGI
BX	TYo
TY	TABo
TSR	TPenn
TQ	TOrd

SHOOTING RECORD

No. of Quarts <u>94</u>	From <u>3510</u>	To <u>3540</u>
<u>135</u>	<u>3785</u>	<u>3780</u>
No. of Quarts <u>120</u>	From <u>3105</u>	To <u>3135</u>
S/	S/	S/
S/	S/	S/
S/	S/	S/

Date	Location	Date	Log
<u>12-4</u>	<u>1425</u>	<u>1-22</u>	<u>W/ Cable too rig</u>
<u>12-11</u>	<u>2300</u>	<u>2-5</u>	<u>TD 3845 prep to plug back</u>
<u>12-18</u>	<u>0 3425</u>	<u>2-12</u>	<u>Prep & perforate</u>
<u>12-31</u>	<u>TD 3790 L Prep to set</u>	<u>2-18</u>	<u>Run log to test</u>
	<u>whipstock @ 3135</u>	<u>2-26</u>	<u>Prep to shut off H₂O</u>
	<u>gas blow out at 3790</u>	<u>3-5</u>	<u>Shut in</u>
<u>1-8</u>	<u>TD 3845 L Prep to</u>	<u>3-12</u>	<u>TD 3945 L TB 3823 Prep to retreat.</u>
	<u>move in cable tools</u>	<u>3-19</u>	<u>TD 3845 L TB 3833 follow 3280</u>
			<u>MC I gas per day thru open 2" log</u>