			1:0			
NO. OF COPIES RECEIVED			****	Form C-103		
DISTRIBUTION		$f_{F_{E}}$				
SANTA FE	NEW MEXICO OIL CO	169 3	C-102 and C Effective 1-1			
FILE				9 55 PM	.	
U.S.G.S.				5a. Indicate Typ	<i>up</i> —	- I
LAND OFFICE				State A	Fee.	<u>-</u>
OPERATOR				5. State Oil & G	ias Lease No.	l
				m	mm	$\overline{\mathcal{T}}$
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "MAPPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)						
1. OIL X GAS WELL WELL	OTHER-			7. Unit Agreeme	nt Name	
2. Name of Operator TEXAS PACIFIC OIL COMPANY				8, Form or Lease Name State "A" A/c-2		
3. Address of Operator P.O. Box 1069 - Hobbs, New Mexico				9. Well No.		
4. Location of Well				10. Field and Pool, or Wildcat		
UNIT LETTER C 990 FEET FROM THE North LINE AND 1650 FEET FROM				South Eunice		
1.7. 1	0	22				$\parallel \parallel \parallel$
THE West LINE, SEC	TION TOWNSHIP	22 RANGE36	NМРМ.			
	15. Elevation (Show whe	ther DF, RT, GR, etc.)		12. County	<u>,,(</u>	17
	3573° DF			Lea		
16. Check	k Appropriate Box To Indicat	e Nature of Notice Repo	ort or Oth	er Data		
	INTENTION TO:			REPORT OF	f:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	X.	ALT	ERING CASING	Щ
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.		PLUG	AND ABANDONMENT	Ш
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JO	je			Г
		OTHER				لــا
OTHER						
17. Describe Proposed or Completed	Operations (Clearly state all pertinen	t details, and give pertinent dates	s, including	estimated date o	f starting any propo	sed
work) SEE RULE 1103.	led made and the Bon	semmeletion and sol	lon lon	2200-2015	•	
	led rods and tbg. Ran '8" 1 JSPF @ 3680-96-371				•	
2. Pen 2 etraddle	packers @ 3632 and 378	21 and fracthe. L	ad hole	w/95 Rbl	. Lease oil.	
Test csg. to 10		a dim iine bes in	964 110±0	, 4, ,, 552	• 10000 011	
4. SOT w/37.800 ga	1. oil and 41,000# sand	l + 1/20 Adomite. Sa	anded ou	it and pac	kers stuck.	
	Wash frac sand.					
5. Ran string shot						
	tor. Pulled tbg. and t	op packer.				
	hoe and milled over.					
	mill. Ran tbg. and gr		om pa c ke	r. Washe	d out sand.	
	@ 3782. Set packer 6		_			
	3770-38451, w/1000 gal					
SOT w/50,000 ga	1. lease oil + 63,000 #	20/40 sand + 1/20 1	Adomite.	•		
11. Washed 15' sand	off HP @ 37821. Clear	ed out sand 38U1-38	42 °	e 2007 t		
12. Ran 120 Jts. (3	702') 2-3/8" tbg. and p HOTR. 1-30-66 22	oor blowd nowb rebart bomb.	Dr Sec	@ 2/2T.•		
19. 12-10-00 2072 E	IMIR. IMJUMU ZA	ing DM/III.				
18. I hereby certify that the information	tion above is true and complete to the	best of my knowledge and belief.				
$A\lambda$	1-1 -	Production Foreman		_	2-1-66	
SIGNED	TITLE			DATE		
1	TITLE	•		DATE		

CONDITIONS OF APPROVAL, IF ANY: