

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-08860

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL  
WELL ☐

GAS  
WELL ☒

OTHER

2. Name of Operator

Meridian Oil Inc.

3. Address of Operator

P.O. Box 51810, Midland, TX 79710-1810

4. Well Location

Unit Letter A : 330 Feet From The North Line and 330 Feet From The East Line

Section 10

Township 22S

Range 36E

NMPM Lea

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3559' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

RU Pride rig. Unsuccessful attempt to plug back and recompleate. Plugged and abandoned well.

6-22-93 - RU Pride rig.

6-23-93 - Set CIBP @ 3742'. Pickle tbq w/250 gls 7 1/2% NEFE HCL acid. Circ hole clean. Pressure tested tbq, failed. Found bad csg from 191-688'. Tstd. csg below 688' to 1000#. Ran GR/Comp Neutron log.

6-25-93 - Ran free point. Chem cut 5 1/2" csg at 695'. Unable to pull csg. Cut csg at 696'. POOH w/21 jts of 5 1/2" csg. Dug out 8 5/8" wellhead, replaced w/new Larkin 8 5/8" x 5 1/2" wellhead.

6-26-93 - dressed up csg cut.

6-28-93 - Circ'd hole clean to 691'. Failed to get over fish. Tbg stuck, could not circ. hole.

6-29-93 - Run freepoint, free pipe down to 671'. Top of fish at 636'. (Fish-shoe, mill, x-sub& 1-4 3/4" DC).

Tbg string plugged. POOH w/tbg. RIH w/3.5" tbg to 636', circ hole w/mud. Screw into fish, begin to work fish, pmpd 12 bbls oil down tbg.

6-30-93 - Jarring, unable to free shoe. Ran freepoint. Free @ 651'. Attempted backoff 3 times, had bad breaks, 4th attempt found tbg plugged, could not get below jars.

7-1-93 - Ran freepoint, free at 578'. POOH w/2-xo subs, jars, bumper, 6-DC's, acc sub, & 3 1/2" tbg. TIH w/3 7/8" bit, tag @ 629'. Drd to 718'. Called OCD Hobbs and obtained verbal approval to P&A well from

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

*Maria L. Perez*

TITLE Production Assistant

DATE 7-7-93

TYPE OR PRINT NAME Maria L. Perez

TELEPHONE NO. 915-688-6906

(This space for State Use)

APPROVED BY

*Charles L. ...*

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

OIL & GAS INSPECTOR

DEC 13 1993

RECEIVED

JUL 09 1993

ACU non-  
1993

Form C103 continuation 7-7-93  
Mattie James #2  
Lea County, NM

Page 2

Mr. Jerry Sexton. Spot 150 sxs "C" cmt. at 718'. Pulled to 353' and spot 35 sxs "C" cmt. Pulled to 30' and spot 15 sxs "C" cmt. to surf. P&A was witnessed by Mr. Charlie Perrin w/OCD. Installed P&A marker, cleaned up location. Well plugged and abandoned.

RECEIVED

JUL 10 1993

COLLEGE  
7-10-93