STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

יום בשורים ויום ויום ויום ויום		, , , , , ,
DISTRIBUTION		
SANTA FE		
FILE		
U.1.C.1.		
LAND OFFICE		
CPPRATOR	Ī	

Ν

me. or Comits Acctives	 OIL CONSERVATION DIVISIO
DISTRIBUTION	P. O. BOX 2088
SANTA PE	SANTA FE, NEW MEXICO 87501
FILE	

Revised 10-1-71	٤
	_

OH & LORD OVAL LE ANY:					
Los Clements Los Clements Oil & Gas Insp.	DATE				
Orig. Signed by					
Dist. Drlg Supt.	DATE 12/02/81				
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.					
•					
pmpd 6 BO, 0 BW & 104 MCFG, GOR 17,333:1. Prior prod: 5 BO, 12 MCFG. FINAL REPORT.					
BP. CO hole to 3796' PBD. RIH w/comp assy, rods & pump. On 24 hr po	otential test 11/17/81				
3541'. Relsd pkr & POH w/tbg & pkr w/plug in place. CO hole to top of BP @ 3718'. POH w/					
10/31/81 SITP 180#. In 7 hr 1.5 BO & 6.5 BW, small show of gas. Set plug in On-Off tool @					
Pulled plug @ 3541'. Frac'd perfs 3667-3706' w/25,000 gal 50/50 Apollo-30 & CO ² , 43,000# sd & flushed w/12 bbls 2% KCL wtr & 12 bbls CO ² . In 1 hr bled dn from 550-0# w/no fluid to surf.					
swbd 0 B0, 23 BW, Set plug in On-Off tool @ 3541'. Relsd tbg from On-Off tool, swbd csg dry					
Acidized perfs 3667-3706' w/1500 gals 15% HCL-NE-LST, flushed w/24 bbls	s 2% KCL wtr. In 3 hrs				
& On-Off tool @ 3541'. Set plug in On-Off tool, relsd plug & swbd tbg	& csg dry, POH w/plug.				
w/l SPF @ 3667, 71, 81, 88, 93, 3701, 06'. RIH w/Lok-set pkr & On-Off tool, set pkr @ 3545'					
csg to 1500# for 30 mins, OK. Spot 200 gals 15% HCL-NE-LST acid 3700-3	:c e 3/10 . Press test 3500'. Perf'd 5½" cea				
Rig up on 10/26/81, POH w/ Comp assy. CO hole to 3790'. RIH w/RBP, se					
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including	estimated date of starting any proposed				
other to prod.					
OTHER Add Perfs same zo	one & treat, return 🔼				
PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JOB	. The Old Obligation				
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING PLUG AND ABANDONMENT				
	ALTERNA STATES				
NOTICE OF INTENTION TO: SUBSEQUENT	REPORT OF:				
Check Appropriate Box To Indicate Nature of Notice, Report or Oth	ner Data				
3553.3' GR	Lea				
15. Elevation (Show whether DF, RT, GR, etc.)	12. County				
THE LINE, SECTION TOWNSHIP RANGE NMPM.					
West 10 22S 36E					
UNIT LETTER M . 560 FEET FROM THE SOUTH LINE AND 660 FEET FROM	Eunice 7R On So				
4. Location of Well	10. Field and Pool, or Wildcat				
P. O. Box 1710-Hobbs, N M 88241-1710	2				
3. Address of Operator	9. Well No.				
Division of Atlantic Richfield Co.	H. S. Record AM				
WELL OTHER-	B. Farm or Lease Name				
1. OIL X CAS OTHER-	7. Unit Agreement Name				
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT —" (FORM C-101) FOR SUCH PROPOSALS.)					
SUNDRY NOTICES AND REPORTS ON WELLS					
DPERATOR 1	5. State Oil & Gas Lease No.				
U.3.C.8.	State Fee X				
1 1	5a. Indicate Type of Lease				