

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
<b>NM 2A</b>

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>TEXAS PACIFIC OIL COMPANY</b>	8. Farm or Lease Name <b>State "A" A/c-2</b>
3. Address of Operator <b>P. O. Box 1069 - Hobbs, New Mexico</b>	9. Well No. <b>16</b>
4. Location of Well UNIT LETTER <b>I</b> <b>2310</b> FEET FROM THE <b>South</b> LINE AND <b>330</b> FEET FROM THE <b>East</b> LINE, SECTION <b>11</b> TOWNSHIP <b>22-S</b> RANGE <b>36-E</b> N.M.P.M.	10. Field and Pool, or Wildcat <b>Arrowhead Grayburg</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3520'</b>	12. County <b>Lea</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work, SEE RULE 1103.

1. Rigged up unit. Killed well. Pulled tubing.
2. Perforated open-hole w/1/4" shots @ 3664-66-68-70-74-78-84-88-92-94-96-98-3700-02-04-18-20-22-24-26-28-30-32-34-46-48-50-52 & 54'. (29 holes)
3. Ran tubing w/packer set at 3600'. Acidized w/5000 gal. 15% NE acid. Flushed w/18 bbl. lease crude.
4. Pulled tubing and packer. Ran 120 jts. 2-3/8" tubing at 3756' w/rods and pump.
5. Placed well on test and recovered load.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original Signed by

SIGNED Sheldon Ward TITLE Area Superintendent DATE 4-16-68

APPROVED BY [Signature] TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: