

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☒ Free ☐

5. State Oil & Gas Lease No.

NM 2A

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator TEXAS PACIFIC OIL COMPANY	8. Farm or Lease Name State "A" A/c-2
3. Address of Operator P. O. Box 1369 - Hobbs, New Mexico	9. Well No. 16
4. Location of Well UNIT LETTER I , 2310 FEET FROM THE South LINE AND 330 FEET FROM THE East LINE, SECTION 11 TOWNSHIP 22-S RANGE 36-E N.M.P.M. Arrowhead	10. Field and Pool, or Wildcat
15. Elevation (show whether DF, RI, GR, etc.) 3520'	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Upon approval, we propose to:

1. Rig up. Full tubing.
2. Perforate open-hole w/1" shots @ 3664-66-68-70-74-78-84-88-92-94-96-98-3700-02-04-18-20-22-24-26-28-30-32-34-46-48-50-52 & 54'. (29 holes)
3. Set packer @ 3600'. Acidize w/5000 gal. 15% NE acid. Flush w/18 bbl. lease crude.
4. Pull tubing and packer. Run tubing, rods and pump.
5. Place well on production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original Signed by

SIGNED Sheldon Ward

TITLE Area Superintendent

DATE 4-8-68

APPROVED BY [Signature]

TITLE _____

DATE _____

CONDITIONS OF APPROVAL, IF ANY: