

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-08850
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-1506
7. Lease Name or Unit Agreement Name State 157 "D"
8. Well No. 4
9. Pool name or Wildcat Eumont Queen Gas

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	
2. Name of Operator ARCO OIL AND GAS COMPANY	
3. Address of Operator P. O. Box 1610, Midland, Texas 79702	
4. Well Location Unit Letter I : 2310 Feet From The South Line and 990 Feet From The East Line Section 12 Township 22 S Range 36 E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3456GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: Add perforations & Stimulate <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to:

1. CO to PBDT 3540
2. Run GR-CCL
3. Perf Eumont f/2652-3086
4. Acidize 2652-3495 w/5000 gals.
5. Swab load.
6. Isolate perfs 2652-3086 & frac w/37,000 gals & 63,000 #sd.
7. Recover load & RIH w/CA.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ken W. Gosnell TITLE Engr. Tech. DATE 4-12-90

TYPE OR PRINT NAME Ken W. Gosnell 915/688-5672 TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
APPROVED BY DISTRICT I SUPERVISOR TITLE DATE APR 18 1990
CONDITIONS OF APPROVAL, IF ANY: