

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-025-08909
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. A-2614
7. Lease Name or Unit Agreement Name McDonald State A/C 2
8. Well No. 26
9. Pool name or Wildcat Eumont (Yates, 7R, Queen)
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3468' GR. 3479' DF

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	
2. Name of Operator Marathon Oil Company	
3. Address of Operator P.O. Box 2409, Hobbs, NM 88240	
4. Well Location Unit Letter J : 1980 Feet From The South Line and 1980 Feet From The East Line Section 13 Township 22-S Range 36-E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3468' GR. 3479' DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Return well to producing status ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5/9 RU pulling unit. POOH w/pump & rods. ND wellhead. NU BOP. POOH w/tbg. RIH w/RBP & pkr. Set RBP at 2700'. pkr at 2660'. Test to 500 psi, OK. Move RBP to 3490, pkr to 2691'. Swab test.
5/15 Rel pkr, RIH, rel RBP. POOH w/both. RIH w/CIBP, set at 3500'. POOH w/setting tool. TIH w/production tbg. ND BOP. NU wellhead. RIH w/pump & rods. Load & test, OK.
5/16 RD pulling unit.

SN at 3463'
Btm of tbg 3481'

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kelly Cook TITLE Records Processor DATE 5/22/00
TYPE OR PRINT NAME Kelly Cook TELEPHONE NO. 505/393-7106

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: