

McDONALD STATE A/C 1 COM NO. 5
DESCRIPTION OF WORKOVER PROCEDURE
(12/12/95 - 12/15/95)

Purpose: Clean out sand fill and run rod pump in gas well to help unload water. Prior to work well was flowing without artificial lift equipment.

- 1. The well was cleaned out to a depth of 3589' and rod pumping equipment installed.**
- 2. Put well on test.**

h:\rep\WOPMCD#5