

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
<u>B-1536</u>

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
2. Name of Operator <u>Conoco Inc.</u>	8. Farm or Lease Name <u>State C</u>
3. Address of Operator <u>P.O. Box 460 - Hobbs, New Mexico 88240</u>	9. Well No. <u>2</u>
4. Location of Well UNIT LETTER <u>I</u> , <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>260</u> FEET FROM THE <u>East</u> LINE, SECTION <u>17</u> TOWNSHIP <u>22S</u> RANGE <u>36E</u> NMPM.	10. Field and Pool, or Wildcat <u>Eunice 7 Bcs Queens</u>
15. Elevation (Show whether DF, RT, GR, etc.)	12. County <u>Lea</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER <u>CO₂ Open Add'l Pay, Stimulate & Return to Production</u>	CASING TEST AND CEMENT JOBS ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) MIRU. POOH w/ rods & pump. Tag for fill & tally out of hole.
- 2) Run csq scraper to 3700' & POOH.
- 3) Clean out to 3850'. Log from 3850'-3000' & POOH.
- 4) Perf w/ 1/4 spf at interval determined from CNL log & POOH.
- 5) Set pki at 3600'. Acidize w/ 90 bbls 15% HCL-NE-FE acid inhibited for 24 hrs at 100° F and 800# graded rock salt mixed in 10 bbls gelled 9th brine in 3 equal stages. Flush w/ 50 bbls 9th brine. Seals well.
- 6) Release pki & POOH.
- 7) Land SN at 3760'. Run producing equipment & place on test. For further information contact Gay Vashler at 397-5866.

I, I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Administrative Supervisor DATE October 7, 1988

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY [Signature] TITLE Geologist DATE OCT 11 1988

CONDITIONS OF APPROVAL, IF ANY: