Budget Bureau 42-R358.2. Approval expires 12-31-52. Land Office Las Cruces

Lease No. 030132 Closson Unit

NOTICE OF I	NTENTION TO DRILL	XX	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF I	NTENTION TO CHANGE PLANS.		SUBSEQUENT REPORT OF SHCOTING OR ACIDIZING.
NOTICE OF I	NTENTION TO TEST WATER SHU	IT-OFF	SUBSEQUENT REPORT OF ALTERING CASING.
NOTICE OF I	NTENTION TO RE-DRILL OR REP	PAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF I	NTENTION TO SHOOT OR ACIDIZ	Æ	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF I	NTENTION TO PULL OR ALTER	CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF I	NTENTION TO ABANDON WELL		
	(INDICATE ABOV	E BY CHECK MARK NATUR	RE OF REPORT, NOTICE, OR OTHER DATA)
		and the same of	LE OF REPORT, NOTICE, OR OTHER DATA)
		Н	obbs, New Mexico October 11 19 37
Well No.	4-1 is located		line and 660 ft. from E line of sec. 18
₩ .ਸ਼.⊮	I.E. 7 Sec. 18	10	line of sec.
(½ Sec.	and Sec. No.)	(Ten)	6—2 N.F.F.A. (Meridian)
South	unice	T.	e) (Meridian)
((Field)	Lea	New Mexico.
Pero -		(County or Subd	
I he elevation	n of the derrick floor a	bove sea level is	7 fr
	ing	- There's strow street, Weigh	its, and lengths of proposed casings; indicate muddings.
is well is	to be drilled to	the big lime t	nts, and lengths of proposed casings; indicate mudding jobs, cement- portant proposed work) which we expect to find at approximately 3
is well is	to be drilled to	the big lime to PROFOSED CASE	which we expect to find at approximately 3
ze	to be drilled to	PROFOSED CAS	which we expect to find at approximately 30 CING PROGRAM Remarks
ze " OD	Teight	PROFOSED CAS Amount 250'	Time Program Remarks To be cemented back to the surface
ze " OD	no se arrited to	PROFOSED CAS	Time Program Remarks To be cemented back to the surface
ze " OD 5/8" OD	Teight	PROFOSED CAS Amount 250'	which we expect to find at approximately 30 CING PROGRAM Remarks
ze " OD -5/8" OD OD	Peight LO# 36#	PROFOSED CAS Amount 250' 1300'	Remarks To be commented back to bottom of surface
ze " OD -5/8" CD	Peight 40# 36# 24#	PROFOSED CAS Amount 250' 1300'	Remarks To be cemented back to the surface To be cemented back to bottom of surface pipe To be cemented back to base of the salt
ze " OD 5/8" OD CD	Peight 40# 36# 24#	PROFOSED CAS Amount 250' 1300' 3675'	Remarks To be cemented back to the surface To be cemented back to bottom of surface pipe To be cemented back to base of the salt
ze " OD 5/8" OD CD	Peight 40# 36# 24#	PROFOSED CAS Amount 250' 1300' 3675'	Remarks To be cemented back to the surface To be cemented back to bottom of surface pipe To be cemented back to base of the salt
ze " OD 5/8" OD CD lunderstand the	Peight 40# 36# 24#	PROFOSED CAS Amount 250' 1300' 3675'	Remarks To be cemented back to the surface To be cemented back to bottom of surface pipe To be cemented back to base of the salt
ze "OD 5/8" OD OD Lunderstand the	Teight 40# 36# 24# at this plan of work must recei	PROFOSED CAS Amount 250' 1300' 3675'	Remarks To be cemented back to the surface To be cemented back to bottom of surface pipe To be cemented back to base of the salt