+Submit 3 Copies

## State of New Mexico

Form C 103 to Appropriate District Office Energy, Munerals and Natural Resources Department Revised 1-1-89 DISTRICT I P.O. Box 1980, Hobbs, NM S8240 OIL CONSERVATION DIVISION WELL API NO. P.O. Box 2088 30-025-08967 Santa Fe, New Mexico 87504-2088 P.O. Drawer DD, Artesia, NM 88210 5. Indicate Type of Lease FEE X STATE DISTRICT T11 1000 Rio Brazos Rd., Aztec, NM 87410 6. State Oil & Gas Lease No. SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Nam ( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE •APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well OTHER South Eunice Unit 2. Name of Operator 8. Well No. Conoco Inc. 3. Address of Operator 9. Pool name or Wildcat 10 Desta Dr. Ste 100W, Midland, Tx., 79705-4500 Eunice 7 Rivers Queen, So. 4. Well Location 1980 Unit Letter H North Feet From The Line and East Feet From The Line Section Township **22S** Range **NMPM** County 10. Elevation (Show whether DF, RKB. RT, GR, etc.) Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON **REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS** COMMENCE DRILLING OPNS. PLUG AND ABANDONMEN **PULL OR ALTER CASING** CASING TEST AND CEMENT JOB OTHER: **OTHER** 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. It is proposed to perform a Casing Integrity Test on this well in preparation for requesting temporary abandonment approval, per the attached recommendation and procedure. When completed, a successful pressure test will be submitted to request temporary abandon status. 12. I hereby certify that the information above is true and complete to the best of my knowledge and belief. Sr. Staff Regulatory Assistant 06/23/99 TYPE OR PRINT NAME Reesa R. Wilkes (this space for **ORIGINAL** SIGNED BY GYBA M' MINK **GARY WINK** 問題。它 REPRESENTATION T FIELD REP. II

Distribution: OCD (3), SHEAR, Ponca, Cost Asst., Well File, Field