

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - A" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name <i>South Eunice Unit</i>
2. Name of Operator <i>Conoco Inc.</i>	8. Farm or Lease Name <i>South Eunice Unit</i>
3. Address of Operator <i>P.O. Box 460 - Hobbs, New Mexico 88240</i>	9. Well No. <i>19</i>
4. Location of Well UNIT LETTER <i>J</i> , <i>1980</i> FEET FROM THE <i>South</i> LINE AND <i>1650</i> FEET FROM THE <i>East</i> LINE, SECTION <i>21</i> TOWNSHIP <i>22S</i> RANGE <i>36E</i> N.M.P.M.	10. Field and Pool, or Wildcat <i>Eunice 7 RYRS Queen G</i>
15. Elevation (Show whether DF, RT, GR. etc.)	12. County <i>Dea</i>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER <i>Clean Out, Open Add'l Pay & Acidize</i> ☒	CASING TEST AND CEMENT JOBS ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

- 1) MIRR. POOH w/ rods & pump. Tag for fill w/ Hg & tally out of hole.
- 2) Clean well out to 3810' & POOH.
- 3) Log from 3800'-3500' & correlate to attached log & POOH.
- 4) Perforate 3628'-3763' w/ 4 jspr for total of 96 shots & POOH.
- 5) Set pku at 3550'. Acidize w/ 90 bbls 15% HCL-NE acid w/ 60 Checker-Sol or equivalent inhibited for 24 hrs at 100°F and 600# graded rock salt mixed in 5 bbls gelled water in 3 equal stages. Flush w/ 80 bbls 9" brine. Swab well.
- 6) Release pku at 3550' & POOH.
- 7) Land SN at 3760'. Run pump & rods & place on test. For further information call Fay Vashler at 397-5866.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *DF FINNEY*

TITLE *Administrative Supervisor*

DATE *9/15/88*

ORIGINAL SIGNED BY JERRY SEXTON

DISTRICT 1 SUPERVISOR

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

SEP 21 1988