


NOBLE AND COMPANY



Company

Shell-Devon

Farm Name

Maar

Sec.

21

Twp

22

Range

36

Well No. 3

County

Feet from Lines: 1980 N.

S. 1980 E.

W.

Elevation

Method

Contractor

O.

Scout

Spudded

Completed

2/1

I. P.

CASING

Gals.

ACID RECORD

131	218	Cement
	150	
1530	-	275
7	2680	- 175

T. A.

T. S.

Prod.

Date

T. P.

B. S.

Date

T. D.

T. L.

320 gals.

2"

3830

DATE

DATE


9-29	TD 230 RB WOC.
10-7	TD 1796 X
10-12	TD 3110 ~ + a
10-20	TD 3608 L
10-27	TD 3720 L
11-3	TD 3830 L trying to deep
11-10	TD 3855 L trying to deep
11-17	TD 3840 L W.O.C. back to 3870 tried 1 H.C. fluid for 10 min. no result
11-23	TD 3840 L W.O.C. Cable logs TE 3840 W.O.C.
12-2	TD 3840 L 320 gals. cleaned to test

2-8	TD 3840 L 320 gals. cleaned to test
12-14	TD 3855 L 320 gals. cleaned to test
12-20	TD 3840 L 320 gals. cleaned to test
12-28	TD 3840 L 320 gals. cleaned to test
1938	5/10 3840 L 320 gals. cleaned to test
1-4	TD 3855 L 320 gals. cleaned to test
JAN 11	TD 3840 L 320 gals. cleaned to test
1-18	TD 3840 L 320 gals. cleaned to test
1-25	TD 3840 L 320 gals. cleaned to test
2-1	TD 3840 L 320 gals. cleaned to test

LOG

[illegible]

NOBLE AND COMPANY



Company

Shell Reunion

Farm Name

Trues

Well No. 3

Sec.

21

Twp

22

Range

36

County

Feet from Lines:

1980 N.

S. 1980 E.

W.

Elevation

Method

Contractor

Oilwell Drilling Co Scout

Spudded

Completed

2/1/

I. P.

CASING

Cement

13'

218

150

9 1/8

1530 - 375

7

3680 - 175

Gals.

3000 gals

no results

Prod.

Date

Prod.

Date

T. A.

T. S.

B. S.

T. L.

T. P.

T. D.

320 gts. gelatin

3720 to 3830

ACID RECORD

DATE		DATE	
9-29	TD 230 R/B W.O.C.	12-8	TD 3840 preparing to make pumping test
10-7	TD 1796 X	12-14	TD 3855 L testing P.B. 3840
10-12	TD 3170 L + a	12-20	TD 3840 SD order pump 9" oil
10-20	TD 3605 L	12-28	TD 3840
10-27	TD 3720 L	1938	SD order
11-3	TD 3830 L preparing to deepen	1-4	TD 3855 L plugged back 3840
11-10	TD 3855 L plugged back to 3840 build 1 lb fluid per hr. 900 water	JAN 11	
11-18	TD 3840 L. M.O. Rotary & M.I. Cable Tools	1-18	
11-29	TD 3840 RUCable Tools	1-25	
12-2	TD 3840 L. Shot 320 gts. Cleaning out to bit	2-7	3855 L plug back P.D. sulphur water

LOG

[illegible]