NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

MISCELLANEOUS NOTICES

Submit this notice in TRIPLICATE to the District Office, Oil Consensation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

	Indicate Nature of Notice by C			
OTICE OF INTENTION O CHANGE PLANS	Notice of Intention to Temporarily Abandon Well	x	Notice of Intention to Drill Deeper	
OTICE OF INTENTION PLUG WELL	Notice of Intention to Plug Back		Notice of Intention to Set Liner	
otice of Intention Squeeze	Notice of Intention to Acidize		Notice of Intention to Shoot (Nitro)	
otice of Intention Gun Perforate	Notice of Intention (Other)		Notice of Intention (Other)	
IL CONSERVATION COMMISSION	N Roswell, New Med	cico	0 ct	ober 3, 1958
entlemen:				
Chall 041	Company Chris	tmas	3A	G
(Company or Ope	Less 21 , T. 22-S , R36-	•	Well No	(Unit)
SW NE /4 of Sec2	21 , T22=S , R36=	NMPM.	, South Eun	1 .09 Pc
Lea	County			
1. Pull 3800' of 2" tub	ing and packer.		REGULATIONS)	
 Leave an 8' sub pack The sub will be bull 	ing and packer. ed off in the tubing anch -plugged and a high press	or.		on the casing.
2. Leave an 8' sub pack. 3. The sub will be bull. 4. Disconnect and pick.	ing and packer. ed off in the tubing anch -plugged and a high press up flow line.	or. ure valv	re will be left o	
2. Leave an 8' sub pack. 3. The sub will be bull. 4. Disconnect and pick	ing and packer. ed off in the tubing anch -plugged and a high press up flow line.	or. ure valv	oil Company Company or Operator	riginal Signed By
2. Leave an 8' sub pack. 3. The sub will be bull. 4. Disconnect and pick. Except as follows:	ing and packer. ed off in the tubing anch -plugged and a high press up flow line. By	or. ure valv	re will be left o	riginal Signed By Rex C. Cabanian
2. Leave an 8' sub pack. 3. The sub will be bull. 4. Disconnect and pick.	ing and packer. ed off in the tubing anch -plugged and a high press up flow line. By	Shel	oil Company Company or Operator C. Cabanies	riginal Signed By Rex C. Cabania