

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-08986

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☐

GAS
WELL ☐

OTHER

Injection

2. Name of Operator

Conoco Inc.

7. Lease Name or Unit Agreement Name

South Eunice Unit

8. Well No.

20

3. Address of Operator

P.O. Box 460 Hobbs, NM 88240

9. Pool name or Wildcat

Eunice 7 Pools. Queen So.

4. Well Location

Unit Letter

I

Feet From The

Line and

Feet From The

Line

Section

21

Township

22S

Range

36E

NMPM

Lea

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Install Liner ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Please disregard previous C-103 to temporarily abandon this well. The work to install liner was completed as follows: Pull out RBP, clean out w/bit and scraper to PBD. Run 4" flush jt. lines. BOL @ 3660'. Pump 150 sks. Class "C" followed by 100 sks. Class "C" w/ 2% CaCl₂. Didn't circ. to surface. Pump down 4" x 5 1/2" annulus. WOC 24 hrs. Perf 4 JSPF @ 3150'. Run CBL top of cmt @ 1650', shoot 4 JSPF @ 1600'. Pumped 150 sks. cmt. Circ. to surf. Squeeze. D.O. cmt to T.D. Set pks. @ 3608'. Stimulate w/90 Bbls 15% HCL-NE-FE. Swab back lead. Set pks @ 3630'. Circ. hole w/pks fluid. Test csq. to 500# for 15 min. Return to injection.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

H. A. Ingram

TITLE

Conservation Coord.

DATE

2/9/90

TYPE OR PRINT NAME

TELEPHONE NO.

397-5800

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

FEB 16 1990