

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN
(Other Instru-
verse side)

PLICATE*
18 OR 20

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Conoco Inc.	8. FARM OR LEASE NAME Meyer B-22
3. ADDRESS OF OPERATOR P.O. Box 460 - Hobbs, New Mexico 88240	9. WELL NO. No. 2
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1650' FWL & 990' FSN - Unit Letter N	10. FIELD AND POOL, OR WILDCAT Hobbs Unit 7 Rev.
14. PERMIT NO. 30-025-08989	15. ELEVATIONS (Show whether DP, RT, GR, etc.)
	11. SEC., T., R., M., OR BLS. AND SURVEY OR AREA 22-22S-36E
	12. COUNTY OR PARISH Lea
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. MIRR. If necessary kill well w/10 lb per gal mud.
2. Run csg scraper to 3139' & tag top of line.
3. Set cement retainers at 3100'. Pump 50 sxs class "C" cement w/2% $CaCl_2$ below retainers from 3100'-3450' and 25 sxs class "C" cement w/2% $CaCl_2$ from 3100'-2850'. Flush w/11 bbls 10#/gal mud. POOH to 2850' & circulate hole w/10#/gal mud. POOH to 1700'. Pump 25 sxs class "C" cement w/2% $CaCl_2$ from 1700'-1450'. Flush w/5 bbls 10#/gal mud.
4. Perf w/4 3/8" P at 600'.
5. Establish injection rate and circulate w/10#/gal mud. If injection rate cannot be established, reperf 50' uphole. Pump 300 sxs class "C" cement w/2% $CaCl_2$ to circulate. POOH. If cement does not circulate, Pump 50 sxs cement down annulus. Cut off wellhead & install PER marker.

18. I hereby certify that the foregoing is true and correct

SIGNED Don Finney JF FINNEY

TITLE Administrative Supervisor

DATE October 12, 1987

THIS SPACE IS FOR FEDERAL OR STATE OFFICE USE

APPROVAL OF
COMMISSIONERS OF APPROVAL, IF ANY:

TITLE

DATE 11-5-87

*See instructions on Reverse Side

Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM-Cable (6) ARCO (2) Amoco (2) Chevron (1) E.P.