

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN
(Other instr
verse side)

YONCATE
DS on re

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

MEXICO 88240

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Conoco Inc.	8. FARM OR LEASE NAME Meier B-22
3. ADDRESS OF OPERATOR P.O. Box 460 - Hobbs, New Mexico 88240	9. WELL NO. No. 3
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' FSH & 660' FWL - Unit Letter L	10. FIELD AND POOL, OR WILDCAT Hobbs / Fulmat Unit 7 Run
14. PERMIT NO. 30-025-08990	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 22-22S-36E
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH Lea
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. MIRU. If necessary, kill well w/10#/gal mud. Run csg scraper to 3350'.
2. Set CIBPat 3300' & test to 500 psi. Pump 25 sxs class 'C' cement w/2% CaCl₂ from 3300'-3050'. POOH to 3050' & circulate hole w/10#/gal mud. POOH to 1800'. Pump 20 sxs class 'C' cement w/2% CaCl₂ from 1800'-1600'. Flush w/5 bbls 10#/gal mud. POOH.
3. Perf at 1550' w/4 jsPF.
4. Establish injection rate & circulate up annulus w/10#/gal mud. If injection rate cannot be established, reperf 50' up hole until injection accomplished. Pump 450 sxs class 'C' cement w/2% CaCl₂ to circulate up annulus. POOH. If cement does not circulate up annulus, pump 25 sxs cement down annulus. Cut off wellhead & install P & A marker.

18. I hereby certify that the foregoing is true and correct

SIGNED John Finney JF FINNEY

TITLE Administrative Supervisor

DATE October 12, 1987

THE SPACE FOR REVIEW OF STATE OFFICE USE

APPROVAL OF
COMMENTS OF APPROVAL, IF ANY:

TITLE

DATE 11-5-87

*See instructions on Reverse Side

The Federal Election Commission makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM-Carlsbad (4) ARCO (2) Amoco (2) Chevron (1) Z.P.

RECEIVED
NOV 6 1997
OCD
HOBBS OFFICE