

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN DUPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER		7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Conoco Inc.		8. FARM OR LEASE NAME Meyer B-22.
3. ADDRESS OF OPERATOR P.O. Box 460 - Hobbs, New Mexico 88240		9. WELL NO. No. 4
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' FSL & 1980' FWL - Unit Letter K		10. FIELD AND POOL, OR WILDCAT Meyer B-22 / Galt Water Gas
14. PERMIT NO. 30-025-08991	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 22-22S-36E
		12. COUNTY OR PARISH Lea
		13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☒
REPAIR WELL ☐	CHANGE PLANE ☐
(Other) ☐	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
(Other) ☐	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. MIRR. If necessary, kill well w/10 lb/gal mud.
2. Run csg scraper to 3250'.
3. Set CIBP at 3200' & test to 500 psi. Pump 25 sxs class 'C' cement w/2% CaCl₂ from 3200' - 2950'. POOH to 2950' & circulate hole w/10 lb/gal mud. POOH.
4. Perforate w/4 jspF at 1650'.
5. Establish injection rate & circulate w/10 lb/gal mud. If injection rate is not established, reperf 50' up hole. Pump 500 sxs class 'C' cement w/18% salt to circulate up annulus & fill csg to surface. POOH. If cement does not circulate, pump 25 sxs cement down annulus.
6. Cut off wellhead & install P&A marker.

18. I hereby certify that the foregoing is true and correct

SIGNED DF Finney

TITLE Administrative Supervisor

DATE October 12, 1987

(This space for Federal or State office use)

APPROVAL OF
COMMITTEES OF APPROVAL, IF ANY:

TITLE

DATE 11-9-87

*See instructions on Reverse Side

31 U.S.C. Section 1061, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM-Caledonia (1) Reno (2) Ammon (2) Charman (1) & P.