

South Eunice Unit No. 27

Page 2

8. Release pkr at 3675' & RBP at 3760'.
9. Set RBP at 3680' & test to 1000 psi via pkr. Set pkr at 3600'. Pump 30 bbls 15% HCl-NE-FE acid plus 50 # graded rock salt mixed in 1 bbl gelled 9# brine. Flush w/ 50 bbls 2% KCl TFW. Swab well.
10. Frac perfs 3641' - 3667' at 15 BPM w/ maximum surface treating pressure of 3000 psi w/ 2000 gals 40# gel water pad & 8,000 gals 40# gel water w/ 20/40 sand. Flush w/ 900 gals 40# gel water. Shut-in. Swab well.
11. Release pkr at 3600' & RBP at 3680' & PCOH.
12. Clean out fill to 3819' & PCOH.
13. Land SN at 3757'. Run producing equipment & place well on production.
If you have any questions, please call Jay Vashler at 393-4141.