

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN 1
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ <u>Injection Well</u>	7. UNIT AGREEMENT NAME <u>South Eunice Unit</u>
2. NAME OF OPERATOR <u>Conoco Inc.</u>	8. FARM OR LEASE NAME <u>South Eunice Unit</u>
3. ADDRESS OF OPERATOR <u>P.O. Box 460 - Hobbs, New Mexico 88240</u>	9. WELL NO. <u>24</u>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) <u>At surface</u> <u>1980' FSL & 660' FFL - Unit Letter I</u>	10. FIELD AND POOL, OR WILDCAT <u>Eunice 7 Rvs Queen, S</u>
14. PERMIT NO. <u>30-025-08998</u>	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <u>22-22S-36 E</u>
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH <u>Lea</u>
	13. STATE <u>NM</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. MIRR. Pressure test backside to 500 psi for 30 mins to test csq integrity, if fails pull up hole 1', t, reset pki & retest. If holds, release Baker AD-1 pki & T00H.
2. Clean out well to 3825' & P00H.
3. Run csq scraper to 3825' & P00H.
4. Run caliper from 3825'-3300' & P00H.
5. Perf intervals 3678'-3770' w/ 2 jsf for total of 68 shots. P00H.
6. Dump 20' of 12/20 sand down csq to plug well back from 3825' to 3680'. G1H w/ bailer & tag sand at 3680'. If sand below 3680', dump additional sand if above 3680'. P00H w/ bailer. G1H w/ 4 3/4" bit & 2 7/8" tbg & reverse out to 3680'. G1H w/ dump bailer & dump 1/2 sx cal-seal plug from 3680'-3675'. WOC 1 hr & tag cmt at 3675' & P00H.
7. G1H w/ Cuiberson 3 1/2" float shoe, float collar, 3 1/2" x 5 1/2" centralizer, 1' x 1' aluminum cmt sub, 5' x 2.812" seal bore extension & 9' tsc 1/2"

18. I hereby certify that the foregoing is true and correct

SIGNED DE FIVEY TITLE Administrative Supervisor

DATE February 5, 1988

(This space for Federal or State office use)

APPROVAL
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

Subject to
Like Approval
by State

*See Instructions on Reverse Side

Title 43 USC Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM-Carlsbad (6) ARCO (2) Amoco (2) Chevron (1) File