OIL CONSERVATION COMMISSION SANTA FE, NEW MEXICO

scellaneous Reports on Wel

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut off, result of plugging of well, and other important operations. tions, results of shooting well, results of test of test of test of the Commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

signed and sworn to before a r		report by checking below.	
REPORT ON BEGINNING DI OPERATIONS	RILLING	REPORT ON REPAIRING WELL	
REPORT ON RESULT OF SE CHEMICAL TREATMENT		REPORT ON PULLING OR OTHE ALTERING CASING	ERWISE
REPORT ON RESULT OF TE SHUT-OFF	ST OF CASING	REPORT ON DEEPENING WELI	
REPORT ON RESULT OF PI	LUGGING OF WELL	Gas Well Report	x
	9-12		
OIL CONSERVATION COMMI SANTA FE, NEW MEXICO. Gentlemen:		Date	Place
	ı.	btained under the heading noted above at the second linit	
		, T 22.8 , R 36.B	N. M. P. M.
•		,	
			<u>-</u>
		tted on Form C-102 on	
			10
		ned. (Cross out incorrect words.)	
DET	AILED ACCOUNT OF WO	RK DONE AND RESULTS OBTAINED	
01 by short to some	1159 A sha 4 0	4 FO	
24 hr. shut in was	1122 7 808. 08 0-2	5-70	
Calculated abs. ope	m flow was 7400 MC	F en 8-28-50	
-			
Note: These tests	were made by El Pa	so Ntl. Gas Co. Engineers	
		-	
Witnessed by			······
vvicilessed by minimum.	Name	Company	Title
Subscribed and sworn before me this		I hereby swear or affirm that the information given above is true and correct.	
20141 841	40 50	Name	
· ,	1950		
Laura	del MATRA	PositionDistrict Engineer	
	Notary Public	RepresentingSun Oil Company of Ope	rator
My commission expires	6-1-5-1	AddressBox 1861, Fidler	d, Israe
		Vine 1	and badea
Remarks:		I LOC 4	annough
9EF		$\mathcal{A} \mathcal{A}$	Name
3 <i>E</i> .		Cill Cha	Income =

Cil Gas Inspe