N M. EN 603. John S. P. O. BOX 1030 P. O. BOX 1030 HOBDS, NEW MEXICO 88240

Form 9-331 Dec. 1973

Form Approved. Budget Bureau No. 42-R1424

UNITED STATES

UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	LC-03/696 (a)
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
Do not use this form for proposals to drill or to deepen or plug back to a different eservoir. Use Form 9–331–C for such proposals.)	NMFU
eservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas Other	SEMU Eumorit 9. WELL NO.
well well other injection well	56
2. NAME OF OPERATOR CONOCO INC.	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR P.O. Box 460, Hobbs, N.M. 88240	Eumont Yates Seven Rivers Queen
P. O. Box 400, Hobbs, N.M. 88240	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	Sec. 25, T-205, R-37E
Lelow.) AT SURFACE: 1980'FSL 7 660' FEL	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL:	Lea N.M.
AT TOTAL DEPTH: V	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF TEST WATER SHUT-OFF	SECONOSIO
FRACTURE TREAT	[1] [31 [V] [4] [1] [1]
SHOOT OR ACIDIZE	
REPAIR WELL UPDATED TO THE PULL OR ALTER CASING UPDATED TO THE PULL OR ALTER CASING UPDATED TO THE PULL OF THE PUL	Chorne on Ford 2330
MULTIPLE COMPLETE	
CHANGE ZONES	OIL & GAS
ABANDON* U	J.S. GECHOGICAL SURVEY ROSMELL, NEW MEXICO
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statincluding estimated date of starting any proposed work. If well is continuous contin	lirectionally drilled, give subsurface locations and
measured and true vertical depths for all markers and zones pertinent to this work.)*	
MIRU	
Release p.Kr. TOOH tog. TIH w/sandline. Fill at 3780!	
Release pri, 100 1 9 12 19 100 Sx	
Set cont retainer at 3583! Squeeze perfs w/ 100 5x	
class "C" cement. Spot 35' cmt. on top of retainer. Pull	
the to 2583', 5pot 100 cmt plug. Pull :	tbg. to 1456', spot
100' cm+ whis POOH cut off 8-5/2" &5-1/2	" csg. Spot 100
cmt. plug. Rig down I move out, clean loca	ation, install PAA mrkr.
Subsurface Safety Valve: Manu. and Type	Set @ Ft.
18. I hereby certify that the foregoing is true and correct	
SIGNED A Bright Mark the foregoing is true and correct SIGNED A Bright Mark the Survey of States of State	ervisor DATE 9-3-82
(This space for rederal or State of	ince use/
APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY:	DATE