NG. OF COPIES RECEIVED	6.6.	Form C-103
DISTRIBUTION	No.	Supersedes Old C-102 and C-103
SANTA FE	NEW MEXICO OIL CONSERVATION COMMESSION	Effective 1-1-65
FILE	anc 2 10 32 mil	,
U.S.3.3.	Nuo -	5a. Indicate Type of Lease
LAND OFFICE	4	State X Fee.
OPERATOR]	5. State Oil & Gas Lease No.
		B - 1616
SUNDS EDU NOT USE THIS FORM FOR PR USE **APPLICAT	RY NOTICES AND REPORTS ON WELLS OPOSALS TO DAILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. TION FOR BERMIT - " FORM C-101) FOR SUCH PROPOSALS.	
GAS WELL	OTHER-	7. Unit Agreement Name
2. Note to the sator		8. Farm or Lease Name
Molon Brunson and E.	. W. Laughlin	State H-17
L. L. Francis Coperator		9. Well No.
P. O. Box 1919, Hobb	os, New Mexico	1
Location of Well		10. Field and Pool, or Wildcat
LANGE TERMER E 1	1650 FEET FROM THE N LINE AND 330 FEET FR	1
·	FEET FROM THE LINE AND FEET FR	MOTORICITY WON
THE W LINE, SECTI	ION 17 TOWNSHIP 20S RANGE 37E NM	PM.
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	3550 DF	
18.		Lea
	Appropriate Box To Indicate Nature of Notice, Report or	
NOTICE OF II	NTENTION TO: SUBSEQUE	INT REPORT OF:
25.5005050		_
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPOHARILY ABANDON PULL OR ALTER CASING	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL ON ALIER CASING	CHANGE PLANS CASING TEST AND CEMENT JQB	_
CTHER	OTHER	
Cidea		
17. Describe Proposed or Completed O	perations (Clearly state all pertinent details, and give pertinent dates, includ	ing estimated date of starting any proposed
work) SEE RULE 1103.		
D-11-4 20 4-3-1	1 1	
Pulled 2" tubing	cleaned out to TD 3790. Shoot Dia-Log string	shot over
peris 3/48 - 3/8	7. Acidize w/2000 gals + 18BS. Swab and test	. After
recovering all I	oad well flowed 40BOPD no water, GOR - 1800.	
3. I checkly costify that the information	above is true and complete to the best of my knowledge and belief.	
i A	A the and complete to the best of my knowledge and belief.	
VA) med	Du d	
7.W. 11. 4	UM FITLE Engineer	DATE 8-2-66
		·
production of the second	TITLE	DAYE