

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

WATER CONSERVATION DIVISION

P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name Cone Jalmat Yates Pool Un
2. Name of Operator J. R. Cone		8. Farm or Lease Name Tract 1
3. Address of Operator Box 871, Lubbock, Tx 79408		9. Well No. 12
4. Location of Well UNIT LETTER <u>E</u> <u>1850</u> FEET FROM THE <u>North</u> LINE AND <u>830</u> FEET FROM THE <u>West</u> LINE, SECTION <u>24</u> TOWNSHIP <u>22-S</u> RANGE <u>35-E</u> NMPM.		10. Field and Pool, or Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 3602 GR; 3614 KB (datum).		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 20 SX Plug 3755' to 3510'. Tag Plug @ 3450'.
- Displace 5½ w/10# Brine & Salt Jel Mud.
- 20 SX Plug 1702 to 1528
- Perf. 5½"-4-½ Holes @ 370'.
- Run & Set 5½ Tension PKR @ 252'. Mix & Pump 50 SX Class "C". Displace to 300'. Tag Plug @ 310'
- 10 SX Plug @ Surf.  
Install D. H. Marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Leonard C. Smith TITLE Agent DATE 8-1-86

APPROVED BY R. H. Hulse TITLE OIL & GAS INSPECTOR DATE SEP 10 1987

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED  
AUG 6 1980  
FBI - NEW YORK

129-170-2111