

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on
reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER Dual		5. LEASE DESIGNATION AND SERIAL NO. LC 031621 (b)
2. NAME OF OPERATOR Continental Oil Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P. O. Box 460, Hobbs, New Mexico		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1630' FNL and 660' FNL, Sec. 15-20-37		8. FARM OR LEASE NAME SEW Blinbry-Tubb
14. PERMIT NO.		9. WELL NO. 85
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3578 DF		10. NAME OF WELL Monument Tubb and Weir Blinbry Pools
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 15, T-20S, R-37E
		12. COUNTY OR PARISH Lea
		13. STATE N. Mex

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

PULL OR ALTER CASING ☐

FRACTURE TREAT ☐

MULTIPLE COMPLETE ☐

SHOOT OR ACIDIZE ☐

ABANDON* ☐

REPAIR WELL ☐

CHANGE PLANS ☐

(Other) **Squeeze and Abandon Blinbry** ☒

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

REPAIRING WELL ☐

FRACTURE TREATMENT ☐

ALTERING CASING ☐

SHOOTING OR ACIDIZING ☐

ABANDONMENT* ☐

(Other) ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The Weir Blinbry was shut-in during January, 1965, because it was uneconomical to produce. On 3-7-67, the Tubb produced 89 BOPD and 48 MOPD. It is proposed to abandon the Blinbry to eliminate communications as follows:

1. Kill Tubb and Blinbry zones w/oil and pull Blinbry tubing.
2. Pull Tubb tubing and tail pipe from Model "D" packer @ 6425'.
3. Drill out Model "D" packer and push below Tubb perforations (Tubb interval 6487-6581').
4. Squeeze Blinbry perforations w/100 an cement, using packer and retrievable SP.
5. Drill out cement and pull retrievable SP.
6. Run Tubb tubing, sub and place on production.

Approval is requested to perform this work. A subsequent report will be filed upon completion of this work.

18. I hereby certify that the foregoing is true and correct

SIGNED

Howard H. Yates

TITLE

District Office Manager

DATE

3-8-67

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED

MAR 8 1967

A. R. BROWN

DISTRICT ENGINEER

DATE

*See Instructions on Reverse Side

USGS-5, Ati-Ros-2, Pan Am-Hobbs-2, Std-Mid-2, File

