

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions on
reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐	M. M. OIL CONS. COMMISSION P. O. BOX 1930 HOBBS, NEW MEXICO 88240	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR AMOCO PRODUCTION COMPANY		8. FARM OR LEASE NAME Gillully "B" Federal 1
3. ADDRESS OF OPERATOR P.O. BOX 68 HOBBS, NEW MEXICO 88240		9. WELL No. 11
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' FNL X 1980' FNL (Unit F, SE 1/4, NW 1/4)		10. FIELD AND POOL, OR WILDCAT Granbury San Andres
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3549' RDB	11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA 22-20-37
		12. COUNTY OR PARISH Lea
		13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	☐	PULL OR ALTER CASING	☐
FRACTURE TREAT	☐	MULTIPLE COMPLETE	☐
SHOOT OR ACIDIZE	☐	ABANDON*	☐
REPAIR WELL	☐	CHANGE PLANS	☐
(Other)			

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	☐	REPAIRING WELL	☐
FRACTURE TREATMENT	☐	ALTERING CASING	☐
SHOOTING OR ACIDIZING	☒	ABANDONMENT*	☐
(Other)			

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

MISW 11-14-84 and RIH w/ 4-3/4" bit and tagged at 3710'. Circ hole clean w/ 270 KCL FW and POH. RIH and perfed 3653'-57', 3661'-67', 3671'-79', 3684'-89' and 3695'-3703' w/ 4 SPF (Perf Diam = .390"), RIH w/ 5 1/2" pkr, SN, and tbg. Pkr SA 3510'. Swabbed well for 4 hrs. and ret pkr and POH. RIH w/ 5 1/2" pkr, SN, and 2-3/8" tbg. Pkr SA 3514'. Acidized w/ 3500 gal 15% HCL, 700 gal Methanol, and 900 # RK salt in 900 gal 30 # gelled brine. Flushed w/ 18 bbl BW. Swabbed well dry. MISW 11-21-84, w/ well S/I. MISW 1-14-85, rel pkr, and POH. RIH w/ 5 1/2" pkr and workstring. Pkr SA 3502. Fraced down tbg w/ 7700 gal fluid and CO2 and 15,800 # SN. Ran swab. Rel pkr, ran tbg and tagged fill at 3682' POH w/ tbg and pkr. RIH w/ 2-3/8" SN, and 2-3/8" tbg. SN LA 3685'. Ran swab 2 hrs

18. I hereby certify that the foregoing is true and correct

SIGNED Th. L. Jeter TITLE Administrative Analyst DATE 5-19-85

(This space for Federal or State office use)

APPROVED BY ACCEPTED FOR RECORD TITLE _____ DATE _____

045-BLM-C, 1-JRB, 1-FJN, 1-NLG
JUN 3 '1985 *See Instructions on Reverse Side

and recovered 16 BLW x NO SG x NO SO. MOSU and MI Swab Unit. Began swabbing well. MO Swab unit 1-21-85 and left well SI. Finished W.O. 5-16-85 w/ well shut-in.