		Form C-103
NO. OF COPIES RECEIVED		Supersedes Old
DISTRIBUTION	C-102 and C-103	
SANTA FE	NEW MEXICONDERVETION COMMISSION	Effective 1-1-65
FILE	JUN 23 11 20 AM '69	5a. Indicate Type of Lease
U.S.G.S.	JUN CO TI ZO AN UD	State Fee X
LAND OFFICE		5. State Oil & Gas Lease No.
OPERATOR		-
SUNDR (DO NOT USE THIS FORM FOR PRO USE "APPLICAT	Y NOTICES AND REPORTS ON WELLS posals to drill or to deepen or plug back to a different reservoir. ion for permit	7. Unit Agreement Name
1.		-
OIL GAS WELL WELL	OTHER-	8. Farm or Lease Name
2. Name of Operator	M.B. Weir 'B'	
TEXACO Inc.		9. Well No.
3. Address of Operator	s, New Maxico 88240	9 -
	3, 10H MAXIO 00210	10. Field and Pool, or Wildcat
4. Location of Well	South 2180	East Welr (Blinebry)
UNIT LETTER ,	660 FEET FROM THE SOUTH LINE AND 2180 FEET FROM	<i></i>
THE East LINE, SECTION	IN 12 TOWNSHIP 20-S RANGE 37-E NMP	
hummmmm	12. County	
	15. Elevation (Show whether DF, RT, GR, etc.)	Lez ///////
^{16.} Check	Appropriate Box To Indicate Nature of Notice, Report or C	Other Data
	NTENTION TO: SUBSEQUE	NT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	
	OTHER	
OTHER		
17 Describe Dropoged of Completed C	Operations (Clearly state all pertinent details, and give pertinent dates, includ	ing estimated date of starting any proposed

17. Describe Propos work) SEE RULE 1103.

TEXACO proposes to do the following work on subject well:

- I. Cut paraffin in Blinebry string.
- Perforate 2-7/8" O.D. w/2 JSPF @ 5888', from 5892'-5896', 5910'-5920', @ 5926', 5946', 2. from 5952'-5959', @ 5978', 5997', and 6010'.
- 3. Acidize new 2-7/8" O.D. casing perforations 5888'-6010' w/2000 gais 15% acid in 5 equal stages using 12 - 5/8" ball sealers between each stage. Precede ist stage w/14 ball sealers to block present perforations.
- Frac down 2-7/8" 0.D. casing w/15,000 gais gelled lease crude in 3 equal stages w/1# 4. 20/40 sand, 1/40# Adomite per dal and 20 gai gel per 1000 gal. Precede ist stage w/14 ball sealers to block present producing interval and follow each stage w/20 ball sealers.
- 5. Swab, test and return to production.

18. I hereby certify that the information above is true and comple	te to the best of my knowledge and belief.	DATE	
APPROVED BY	Assistant District Superintendent	DATE	June 23, 1969

TEXACO Inc.		*• <u>.</u>	
U.S.G.S. JUN 2.3 II 20 AM '59 State Type of Lease OPERATOR SUNDRY NOTICES AND REPORTS ON WELLS State I Prec X ID NOT USE THIS FORM TO PROPOSALE TO CHILL ON TO OPERAT OA DUFFERENT RESERVOIR. 7. Unit Agreement Name USE "MARENDA FOR TRANSPORT CONTROL ON TO OPERAT OA DUFFERENT RESERVOIR. 7. Unit Agreement Name	DISTRIBUTION	NEW MEXICO OIL CONSERVATION COMMISSION	Supersedes Old C-102 and C-103
LAND OFFICE		Jun 23 11 20 AM '69	
1. OTHER. OTHER. Image: Comparison of Operator Image: Comparison of Operator 2. Name of Operator 8. Parm or Lease Name M.B. Weir 'B' 3. Address of Operator 9 4. Location of Well 9 UNIT LETTER 0 660 PEET FROM THE South Line and 2180 FEET FROM THE East LINE, SECTION 15. Elevation (Show whether DF, RT, GR, etc.) 12. County 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS CHANGE PLANS OTHER OTHER			
WELL OTHER- 8, Form or Lease Name 2, Name of Operator M, B, Weir 'B' TEXACO Inc. 9, Well No. 3, Address of Operator 9, Well No. P.O. Box 728 - Hobbs, New Mexico 88240 9 4, Location of Well 0 UNIT LETTER 0 660 FEET FROM THE South 2180 THE East LINE, SECTION 12 Township 20-S RANGE 37-E NMPM. 15, Elevation (Show whether DF, RT, GR, etc.) 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON OTHER CHANGE PLANS OTHER CHANGE PLANS	1.	RY NOTICES AND REPORTS ON WELLS OPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. TION FOR PERMIT	7, Unit Agreement Name
3. Address of Operator 9 4. Location of Well 0 660 FEET FROM THE South 2180 FEET FROM Skaggs Drinkard THE East LINE, SECTION 12 TOWNSHIP 20-S RANGE 37-E NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 15. Elevation (Show whether DF, RT, GR, etc.) 12. County Lea 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING PULL OR ALTER CASING CHANGE PLANS OTHER OTHER	2. Name of Operator	OTHER-	M.B. Weir 'B'
4. Location of Well 0 660 FEET FROM THE South LINE AND 2180 FEET FROM Skaggs Drinkard THE East LINE, SECTION 12 TOWNSHIP 20-S RANGE 37-E NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 15. Elevation (Show whether DF, RT, GR, etc.) 12. County Lea 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK X Altering casing PULL OR ALTER CASING CHANGE PLANS CHANGE PLANS OTHER OTHER		s, New Mexico 88240	9
THE East 12 TOWNSHIP 20-S RANGE 37-E NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 15. Elevation (Show whether DF, RT, GR, etc.) 12. County 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON PULL OR ALTER CASING CHANGE PLANS OTHER OTHER	0	660 FEET FROM THE South LINE AND 2180 FEET	Skaggs Drinkard
3565' (D.F.) Lea 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON PERFORM REMEDIAL WORK PLUG AND ABANDON PULL OR ALTER CASING CHANGE PLANS OTHER OTHER		10N 12 TOWNSHIP 20-S RANGE 37-E	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS OTHER COMMENCE DRILLING OPNS.			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JQB OTHER OTHER			r Other Data JENT REPORT OF:
	TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
		Operations (Clearly state all pertinent details, and give pertinent dates, inc	luding estimated date of starting any proposed

The following work has been completed on subject well:

- Pull production rods.
 Perforate 2-7/8" O.D. Casing (Drinkard) w/2 JSPF from 6782'-6793' and 6799'-6803'.
- Acidized w/4000 gals 15% NE acid in four equal stages using 15# unibeads between 3.
- stages.
- Swab, test and return to production. 4.

Δ	Note the best of my knowledge and belief.	
18. I hereby certify that the information above is true and co		DATE
APPROVED BY	Assistant District	DATE June 23, 1969
CONDITIONS OF APPROVAL, IF AND		