

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

LC 031695 (b)

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME Warren	
2. NAME OF OPERATOR Continental Oil Company		8. FARM OR LEASE NAME Warren Unit	
3. ADDRESS OF OPERATOR Box 460, Hobbs, New Mexico		9. WELL NO. 29	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FNL & 660' FEL, Sec. 33, T-20S, R-38E, Lea County, New Mexico, NMPM		10. FIELD AND POOL, OR WILDCAT Wildcat	
14. PERMIT NO.		12. COUNTY OR PARISH Lea	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3534 DF		13. STATE N.M.	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input checked="" type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	(Other) <input type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The subject well was tested and found to be commercially non-productive. It is proposed to plug and abandon this well using the following procedure:

1. Pull retrievable bridge plug at 3,500'
2. Set cement plugs as follows W/10# mud between plugs.
4075-4220 15 sx Class "C" -
3395-3540 15 sx Class "C" -
2840-3010 20 sx Class "C" -
3. Cut 5 1/2" at approximately 2640' and pull.
4. Set cement plug as follows W/10# mud in between.
2500' to 2665' - 50 sx Class "C"
1375' to 1485' - 50 sx Class "C"
0 to 25' - 10 sx Class "C"
5. Restore the location as nearly as possible to its original condition and erect a 4" pipe marker with the name and location inscribed thereon.

On 1-21-65 verbal approval from Mr. Brown at USGS to V. T. Lyon.

18. I hereby certify that the foregoing is true and correct

SIGNED SIGNED: ROBERT GAULT III TITLE Staff Supervisor DATE 1-22-65

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

USGS-5, NMOCC-2, JM PAN AM HOBBS-3, ATL-ROS-2, CALIF

*See Instructions on Reverse Side

