

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO CEASE OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101, FOR SUCH PROPOSALS.)		5a. Indicate Type of Lease State ☐ Fee ☐
1. Name of Operator TEXACO Inc.		5. State Oil & Gas Lease No. -
2. Address of Operator P.O. Box 728, Hobbs, New Mexico 88240		7. Unit Agreement Name -
3. Location of Well UNIT LETTER A 660 FEET FROM THE East LINE AND 660 FEET FROM THE North LINE, SECTION 10 TOWNSHIP 20-S RANGE 37-E NMPM.		8. Farm or Lease Name E.H.B. Phillips "C"
15. Elevation (Show whether DF, RT, GR, etc.) 3621' (DF)		9. Well No. 1
10. Field and Pool, or Wildcat Weir Blinebry		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐ PLUG OR ALTER CASING ☐ OTHER ☒ Abandon Blinebry-Recompl in Eumont Queen Gas	PLUG AND ABANDON ☐ CHANGE PLANS ☐ OTHER ☒	REMEDIAL WORK ☐ COMMENCE DRILLING OPNS. ☐ CASING TEST AND CEMENT JOBS ☐ OTHER ☐	ALTERING CASING ☐ PLUG AND ABANDONMENT ☐ OTHER ☐
---	--	---	--

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up. INSTALL BOP.
2. Set CIBP @ 5750' & dump 10' cement on top of plug.
3. Selectively perforate 2-7/8" OD csg. w/2 JSPF in an interval of 3555'-3795'.
4. Acidize perforations w/3000 gals 15% NE Acid.
5. Install producing equipment, test, & place on production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

DATE 2-22-77	TITLE Asst. Dist. Supt.
DATE 2/24/78	TITLE Operator

CONDITIONS OF APPROVAL, IF ANY: