NO. OF COPIES RECEIVED		Ford C 100
DISTRIBUTION		Form C-103 Supersedes Old
SANTA FE	NEW MEXICO OIL CONSERVATION COMMIS	C-102 and C-103
FILE	MEMILARIO OTE CONSERVATION COMMIS	SION Effective 1-1-65
U.S.G.S.		5a. Indicate Type of Lease
LAND OFFICE		
OPERATOR		5. State Oil & Gas Lease No.
SUNDR'	Y NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROF USE "APPLICATI	Y NOTICES AND REPORTS ON WELLS posals to drill or to deepen or plug back to a different re on for permit -" (form C-101) for such proposals.)	SERVOIR. ())))))))))))))))))))))))))))))))))))
		7. Unit Agreement Name
WELL WELL	OTHER-	-
2. Name of Operator		8. Farm or Lease Name
TEXACO Inc.		M. B. Weir 'B'
3. Address of Operator		9. Well No.
P.O. Box 728, Hobbs	s, New Mexico 88240	10
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER P	987 East 990	East Weir Blinebry
THE LINE, SECTION	12 TOWNSHIP 2.0S RANGE 37E	
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
inninninninninninninninninninninninninn	3565' DF	Lea ())))))))
<sup>16.</sup> Check A		
16. Check A NOTICE OF IN	ppropriate Box To Indicate Nature of Notice,	Report or Other Data
16. Check A NOTICE OF IN	ppropriate Box To Indicate Nature of Notice,	
16. Check A NOTICE OF IN	ppropriate Box To Indicate Nature of Notice,	Report or Other Data SUBSEQUENT REPORT OF:
NOTICE OF IN	PLUG AND ABANDON REMEDIAL WORK	Report or Other Data SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	Report or Other Data SUBSEQUENT REPORT OF: ALTERING CASING PNS. PNS. PLUG AND ABANDONMENT
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	Report or Other Data SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK CHANGE PLANS	Report or Other Data SUBSEQUENT REPORT OF:

work) SEE RULE 1103.

TEXACO Inc. proposes to do the following work on subject well:

- 1. Orient and perforate w/2 JSPF from 5920-29, 5950-59 and 5986-90', 2 JSPI @ 6009, 28, 32 and 36', 2 JSPF from 6075-86'.
- 2. Acidize w/3000 gal 15% NEA in 10 equal stages.
- 3. Frac new perforations w/20,000 gals gelled lease crude in 8 equal stages. Use 1 ppg 20/40 sand, 25 lb/1000 gal Mark II Adomite and 50 lb/1000 gal gelling agent.
- 4. Swab, test and place on production.

18. I hereby certify that the information above is true and complet	e to the best of my knowledge and belief. Assistant District Superintende	Sontonhan 1 1071
APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	TITLE SUPERVISOR DISTRICT 1 DATE	SEP 3 1971

RECEIVED SEP 21971 OIL CONSERVATION COMM. HOBBS, N. M.

· •

. .

u**∉** 1 ≱ .

3: