Form 3 160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

Marin War State State Confidence	Will College to see the contribution of the college
STATES	P.O. P. BURNEW MENDE -0135
TMENT OF THE INTERIOR	P.O. Budestale ARE 1004-0135
J OF LAND MANAGEMENT	HORBELL Everings: March 21, 1003

		5. Lease Designation and Serial No.
STANDEN NO	OTIOES AND DEDOOTS ON WELLS	LC 031621B
	OTICES AND REPORTS ON WELLS or to deepen or reentry to a different reservoir.	6. If Indian, Allottee or Tribe Name
Use "APPLICATION FOR PERMIT	or to deepen or reentry to a different reservoir. —— for such proposals	
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation
Type of Well		
Well Well Other		B. Well Name and No.
CONOCO INC.		BRITT B #24
ddress and Telephone No.		
10 DESTA DR. STE 100W, MIDLAND, TX. ocation of Well (Footage, Sec., T., R., M., or Survey Dee	79705 (915) 686 – 5424	30 - 0/25 - 21 223 10. Field and Pool, or Exploratory Area
SURFACE: 1990' FSL & 660' FWL, SEC. 11, T 20S, R 37E, UNIT LTR 'L' TD:		MONUMENT TUBB
		11. County or Parish, State
		LEA, NM
CHECK APPROPRIATE BOX(s)	TO INDICATE NATURE OF NOTICE, REPO	RT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACT	TION
Notice of Intent	Abandonment	Change of Plans
	Recompletion	New Construction
X Subsequent Report	Plugging Back	Non-Routne Fracturing
Final Abandonment Notice	X Casing Repair	Water Shut-Off
	Altering Casing	Conversion to injection
	Other	Dispose Water
		Alch: Reportments of multiple accordation on third
1 – 24 – 95 MIRU. POOH W/ PUMP, R RUN CSG TEST. PUMP 3 bbl MT DO	itate all pertinent details, and give pertinent dates, including estimated dimeasured and true vertical depths for all markers and zones pertinent to RODS & TBG. GIH W/RBP SET @ 6430' & PACHOWN SURFACE CSG. RELEASE PACKER & RBI	this work.)* KER
1 – 24 – 95 MIRU. POOH W/ PUMP, R RUN CSG TEST. PUMP 3 bbl MT DO GIH W/ TBG, PUMP & RODS.	itate all pertinent details, and give pertinent dates, including estimated dimeasured and true vertical depths for all markers and zones pertinent to RODS & TBG. GIH W/RBP SET @ 6430' & PACHOWN SURFACE CSG. RELEASE PACKER & RBI	Completion or Recompletion Report and Log form.) ate of starting arry proposed work. If well is this work.)*
1 – 24 – 95 MIRU. POOH W/ PUMP, R RUN CSG TEST. PUMP 3 bbl MT DO	itate all pertinent details, and give pertinent dates, including estimated dimeasured and true vertical depths for all markers and zones pertinent to RODS & TBG. GIH W/RBP SET @ 6430' & PACHOWN SURFACE CSG. RELEASE PACKER & RBI	Completion or Recompletion Report and Log form.) ate of starting arry proposed work. If well is this work.)*
1 – 24 – 95 MIRU. POOH W/ PUMP, R RUN CSG TEST. PUMP 3 bbl MT DO GIH W/ TBG, PUMP & RODS.	itate all pertinent details, and give pertinent dates, including estimated dimeasured and true vertical depths for all markers and zones pertinent to RODS & TBG. GIH W/RBP SET @ 6430' & PACHOWN SURFACE CSG. RELEASE PACKER & RBI	Completion or Recompletion Report and Log form.) ate of starting arry proposed work. If well is this work.)*
1 – 24 – 95 MIRU. POOH W/ PUMP, R RUN CSG TEST. PUMP 3 bbl MT DO GIH W/ TBG, PUMP & RODS.	itate all pertinent details, and give pertinent dates, including estimated dimeasured and true vertical depths for all markers and zones pertinent to RODS & TBG. GIH W/RBP SET @ 6430' & PACHOWN SURFACE CSG. RELEASE PACKER & RBI	Completion or Recompletion Report and Log form.) ate of starting arry proposed work. If well is this work.)*
I -24-95 MIRU. POOH W/ PUMP, R RUN CSG TEST. PUMP 3 bbl MT DO GIH W/ TBG, PUMP & RODS.	itate all pertinent details, and give pertinent dates, including estimated dineasured and true vertical depths for all markers and zones pertinent to RODS & TBG. GIH W/ RBP SET @ 6430' & PACHOWN SURFACE CSG. RELEASE PACKER & RBI	Completion or Recompletion Report and Log form.) ate of starting arry proposed work. If well is this work.)*
I -24-95 MIRU. POOH W/ PUMP, R RUN CSG TEST. PUMP 3 bbl MT DO GIH W/ TBG, PUMP & RODS. 1-26-95 RDMO. RETURN WELL	itate all pertinent details, and give pertinent dates, including estimated dineasured and true vertical depths for all markers and zones pertinent to RODS & TBG. GIH W/ RBP SET @ 6430' & PACHOWN SURFACE CSG. RELEASE PACKER & RBI	Completion or Recompletion Report and Log form.) ate of starting any proposed work. If well is this work.)* KER P, POOH.
I -24-95 MIRU. POOH W/ PUMP, R RUN CSG TEST. PUMP 3 bbl MT DO GIH W/ TBG, PUMP & RODS.	itate all pertinent details, and give pertinent dates, including estimated dineasured and true vertical depths for all markers and zones pertinent to RODS & TBG. GIH W/ RBP SET @ 6430' & PACHOWN SURFACE CSG. RELEASE PACKER & RBI	Completion or Recompletion Report and Log form.) ate of starting arry proposed work. If well is this work.)*
I -24-95 MIRU. POOH W/ PUMP, R RUN CSG TEST. PUMP 3 bbl MT DO GIH W/ TBG, PUMP & RODS. 1-26-95 RDMO. RETURN WELL	itate all pertinent details, and give pertinent dates, including estimated dineasured and true vertical depths for all markers and zones pertinent to RODS & TBG. GIH W/ RBP SET @ 6430' & PACHOWN SURFACE CSG. RELEASE PACKER & RBI	Completion or Recompletion Report and Log form.) ate of starting any proposed work. If well is this work.)* KER P, POOH.
1-24-95 MIRU. POOH W/ PUMP, R RUN CSG TEST. PUMP 3 bbl MT DO GIH W/ TBG, PUMP & RODS. 1-26-95 RDMO. RETURN WELL	itate all pertinent details, and give pertinent dates, including estimated dineasured and true vertical depths for all markers and zones pertinent to RODS & TBG. GIH W/ RBP SET @ 6430' & PACHOWN SURFACE CSG. RELEASE PACKER & RBI	Completion or Recompletion Reput and Log form.) ate of starting any proposed work. If well is this work.)* KER P, POOH.
1-24-95 MIRU. POOH W/ PUMP, R RUN CSG TEST. PUMP 3 bbl MT DO GIH W/ TBG, PUMP & RODS. 1-26-95 RDMO. RETURN WELL	intate all pertinent details, and give pertinent dates, including estimated diseasured and true vertical depths for all markers and zones pertinent to RODS & TBG. GIH W/ RBP SET @ 6430' & PACH DWN SURFACE CSG. RELEASE PACKER & RBI TO PRODUCTION. ACCEPTED FOR RECORD J. Jun. 6 1995	Completion or Recompletion Reput and Log form.) ate of starting any proposed work. If well is this work.)* KER P, POOH.
1-24-95 MIRU. POOH W/ PUMP, R RUN CSG TEST. PUMP 3 bbl MT DO GIH W/ TBG, PUMP & RODS. 1-26-95 RDMO. RETURN WELL	itate all pertinent details, and give pertinent dates, including estimated dineasured and true vertical depths for all markers and zones pertinent to RODS & TBG. GIH W/ RBP SET @ 6430' & PACHOWN SURFACE CSG. RELEASE PACKER & RBI	Completion or Recompletion Reput and Log form.) ate of starting any proposed work. If well is this work.)* KER P, POOH.
I -24-95 MIRU. POOH W/ PUMP, R RUN CSG TEST. PUMP 3 bbl MT DO GIH W/ TBG, PUMP & RODS. 1-26-95 RDMO. RETURN WELL	intate all pertinent details, and give pertinent dates, including estimated diseasured and true vertical depths for all markers and zones pertinent to RODS & TBG. GIH W/ RBP SET @ 6430' & PACH DWN SURFACE CSG. RELEASE PACKER & RBI TO PRODUCTION. ACCEPTED FOR RECORD J. Jun. 6 1995	Completion or Recompletion Reput and Log form.) ate of starting any proposed work. If well is this work.)* KER P, POOH.
1-24-95 MIRU. POOH W/ PUMP, R RUN CSG TEST. PUMP 3 bbl MT DO GIH W/ TBG, PUMP & RODS. 1-26-95 RDMO. RETURN WELL	intate all pertinent details, and give pertinent dates, including estimated diseasured and true vertical depths for all markers and zones pertinent to RODS & TBG. GIH W/ RBP SET @ 6430' & PACH DWN SURFACE CSG. RELEASE PACKER & RBI TO PRODUCTION. ACCEPTED FOR RECORD J. Jun. 6 1995	Completion or Recompletion Reput and Log form.) ate of starting any proposed work. If well is this work.)* KER P, POOH.
1-24-95 MIRU. POOH W/ PUMP, R RUN CSG TEST. PUMP 3 bbl MT DO GIH W/ TBG, PUMP & RODS. 1-26-95 RDMO. RETURN WELL	intate all pertinent details, and give pertinent dates, including estimated diseasured and true vertical depths for all markers and zones pertinent to RODS & TBG. GIH W/ RBP SET @ 6430' & PACH DWN SURFACE CSG. RELEASE PACKER & RBI TO PRODUCTION. ACCEPTED FOR RECORD J. Jun. 6 1995	Completion or Recompletion Reput and Log form.) ate of starting any proposed work. If well is this work.)* KER P, POOH.
1-24-95 MIRU. POOH W/ PUMP, R RUN CSG TEST. PUMP 3 bbl MT DO GIH W/ TBG, PUMP & RODS. 1-26-95 RDMO. RETURN WELL	intate all pertinent details, and give pertinent dates, including estimated diseasured and true vertical depths for all markers and zones pertinent to RODS & TBG. GIH W/ RBP SET @ 6430' & PACH DWN SURFACE CSG. RELEASE PACKER & RBI TO PRODUCTION. ACCEPTED FOR RECORD J. Jun. 6 1995	Completion or Recompletion Reput and Log form.) ate of starting any proposed work. If well is this work.)* KER P, POOH.
1-24-95 MIRU. POOH W/ PUMP, R RUN CSG TEST. PUMP 3 bbl MT DO GIH W/ TBG, PUMP & RODS. 1-26-95 RDMO. RETURN WELL	itate all pertinent details, and give pertinent dates, including estimated dineasured and true vertical depths for all markers and zones pertinent to RODS & TBG. GIH W/ RBP SET @ 6430' & PACH DWN SURFACE CSG. RELEASE PACKER & RBI TO PRODUCTION. ACCEPTED FOR RECORD J. June 6 1995	Completion or Recompletion Reput and Log form.) ate of starting any proposed work. If well is this work.)* KER P, POOH.
1-24-95 MIRU. POOH W/ PUMP, R RUN CSG TEST. PUMP 3 bbl MT DO GIH W/ TBG, PUMP & RODS. 1-26-95 RDMO. RETURN WELL hereby certify that the foregoing is true and correct	itate all pertinent details, and give pertinent dates, including estimated dineasured and true vertical depths for all markers and zones pertinent to BODS & TBG. GIH W/ RBP SET @ 6430' & PACHOWN SURFACE CSG. RELEASE PACKER & RBI TO PRODUCTION. ACCEPTED FOR RECORD J. June 6 1995	Completion or Recompletion Reput and Log form.) ate of starting any proposed work. If well is this work.)* KER P, POOH.
1-24-95 MIRU. POOH W/ PUMP, R RUN CSG TEST. PUMP 3 bbl MT DO GIH W/ TBG, PUMP & RODS. 1-26-95 RDMO. RETURN WELL	itate all pertinent details, and give pertinent dates, including estimated dineasured and true vertical depths for all markers and zones pertinent to RODS & TBG. GIH W/ RBP SET @ 6430' & PACH DWN SURFACE CSG. RELEASE PACKER & RBI TO PRODUCTION. ACCEPTED FOR RECORD J. June 6 1995	Completion or Recompletion Reput and Log form.) ale of starting any proposed work. If well is this work.)* KER P, POOH. MAR 13 1995
1-24-95 MIRU. POOH W/ PUMP, R RUN CSG TEST. PUMP 3 bbl MT DO GIH W/ TBG, PUMP & RODS. 1-26-95 RDMO. RETURN WELL hereby certify that the foregoing is true and correct	itate all pertinent details, and give pertinent dates, including estimated dineasured and true vertical depths for all markers and zones pertinent to RODS & TBG. GIH W/ RBP SET @ 6430' & PACH DWN SURFACE CSG. RELEASE PACKER & RBI TO PRODUCTION. ACCEPTED FOR RECORD J. June 6 1995	Completion or Recompletion Reput and Log form.) ale of starting any proposed work. If well is this work.)* KER P, POOH. MAR 13 1995