

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Injection Well		7. Unit Agreement Name Grama Ridge Morrow
2. Name of Operator Llano, Inc.		8. Farm or Lease Name State GRA Com
3. Address of Operator P. O. Box 1320, Hobbs, New Mexico 88240		9. Well No. One
4. Location of Well UNIT LETTER <u>E</u> , <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>3</u> TOWNSHIP <u>22-S</u> RANGE <u>34-E</u> NMPM.		10. Field and Pool, or Wildcat Grama Ridge
15. Elevation (Show whether DF, RT, GR, etc.) 3630' GR		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER <u>Convert to injection well</u> <input checked="" type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Ran tbg plug and perfd tbg @ 11,790'.
2. Cired oil from annulus w/wtr and pulled tbg.
3. Re-ran tbg with Baker "on-off" tool on top of latch-in seal assembly with plug in place.
4. Loaded hole with 2% KCL wtr and latch on to tbg.
5. Swbd dwn tbg and pulled plug.
6. Well ready for injection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Donald L. Lary TITLE Vice President DATE 9/17/73

APPROVED BY Joe D. Blaney TITLE Director DATE 9/17/73

CONDITIONS OF APPROVAL, IF ANY: None